8-21

4-032281 15-153-20005-00-01

TO:	API Number:15 1958
STATE CORPORATION COMMISSION	G GT4
CONSERVATION DIVISION - PLUGGING 130 SOUTH MARKET, SUITE 2078	C SW/4 SEC05,_01_,_33_W 1320 feet from S section line
WICHITA KANGAG 67202	3960 feet from E section line
Operator: Northwest Well Service	1000 110m 1 Becelon 11me
Operator license# 31664 #3 an4	Lease: Palmer Well # B-1
Operator: Northwest Well Service	County: Rawlins 135.36
Address: 1/509 County Road - #14 Fort Morgan, CO 80701	Well total depth 4165 feet Conductor Pipe: 0 inch 0 0 feet Surface pipe 8 5/8 Inch 0 203 feet
Aband. oil well_x_, Gas well, Input well	, SWD, D & A
Plugging contractor: Company Tools	License# <b>31664</b>
Address: 17509 County Road #14 - Fort Morga	n, CO 80701
Company to plug at: Hour: P.M. Day: 21	Month: August Year: 1997
Plugging proposal received from: Randy	
Company: Northwest Well Service	Phone:
Were: Order 200 sxs 60/40 pozmix - 10% gel - 500# hulls. Allied Cement Company. Order B.P. and common cement.	
Plugging Proposal Received by: Carl Goodre Plugging operations attended by agent? All[  Completed: Hour:11:00 A.M., Day:21 Month:  Actual plugging report: 8 5/8" set at 203' w/1  Prod. Perfs at 3832' - 3837'. Set B.P. at 3780  2190' - 1650' and 900'. Recovered 900' of 4 1/2  blend with 300# hulls. Mixed into Max. P.S.I.	], Part[X], None[]  August , Year: 1997  00 sxs cwc. 4 1/2" set at 4154' with N/A sxs 0' w/25 sxs common cement on plug. Shots at " casing. Squeezed 8 5/8" with 80 sxs cement
Domo vilor	87AFE ( 1-7-9 8
Remarks:BAD_ Condition of casing(in hole): GOODBAD_	
Bottom plug(in place): YES, CALC, Plugged through TUBING, CASING	NO Dakota plug YES X . NO
I dim[ V 0/10th Eof ] observe the plugging.	Carl Goodion
JAN 0 8 1998	(agent)
10001	Form CP-2/3