DISTRICT CONSERVATION AGENT'S REPORT



TO:

15-137-00254-00-00

State Corporation Commission Conservation Division

211 North Broadway			FILE NO.
Wichita, Kansas			LOCATION SE SE NE
			SEC. 33 TWP. 3 RGE. 23 W
Dry Hole X Abandone	d Oil Well	Abandoned	Gas Well
I have this date completed	supervision of p	lugging of:	
Well No. 1 Lease	Le Beau	·	
Operator Jones, Shelburne	Farmer & MA	dress	Russell, Kans
Field	Co	unty	Norton
Total Depth 3784	Feet.		
Plugging Contractor Sa	ıme		
Plugging Contractor's Licen	se No		
Address			
(Describe br 8 5/8" at 276' circu	iefly the manner lated with $\mathbf{c} \in$	in which to	he well was plugged)
			ing plug at 270', 1/2
sack hulls and 15 sa	ux cement, mud	to 40',	set cementing plug,
1/2 sack hulls and I	LO sax cement	to bottom	cellar.
			Maria de Maria de Maria de Arte de Art
			Cedent Lieu
and the second s			trict Conservation/Agent -4-56
HINGGING PORT	in the second of	Doto	

一起舞蹈的转列。 到50 位在200

4-9-56