KANSAS

STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT
15-039-20098-00-00

J. Lewis Brock Administrator 500 Insurance Building Wichita, Kansas 67202

Lease Name Charles Well No. 2 Location CNE-NE Sec. 29 Twp. 3 Rge. (E) (W) County Decatur Total Depth 3956: Abandoned Cil Well Gas Well Input Well SWD Well D&A X Other well as hereafter indicated Plugging Contractor Abercrombie Drilling, Incorporated, Address 801 Union Center Building, Wichita, Kansas. License No. Operation Completed: Hour 7:00 AM Day 16 Month 7 Year 1969 The above well was plugged as follows: 261:-8 5/8" Surface casing, cement circulated with 200 Sx. Top of Dakota section © 1800. Circulated hole with heavy mud. Pulled DP to 2000 and displaced 100 Sx. cement the DP from 2000: to 1675:. Pulled DP to 275; and displaced 20 Sx. cement thru DP from 275; to 215:, Pulled DP, set bridge @ ho! with 1 sack hulls and 10 Sx. cement to bottom of cellar. RECEIVED STATE CORPORATION DIVISION Wichita, Kansas 2 - 69 Well Plugging Supervisor	AND	•	,		•	
County Decatur Total Depth 3956: Abandoned Oil Well Gas Well Input Well SWD Well D&A X Other well as hereafter indicated Plugging Contractor Abercrombie Drilling, Incorporated, Address 801 Union Center Building, Wichita, Kansas. License No. Operation Completed: Hour 7:00 AM Day 16 Month 7 Year 1969 The above well was plugged as follows: 261:-8 5/8" Surface casing, cement circulated with 200 Sx. Top of Dakota section © 1800'. Circulated hole with heavy mud. Pulled DP to 2000'and displaced 100 Sx. cement the DP from 2000' to 1675'. Pulled DP to 275' and displaced 20 Sx. cement thru DP from 275' to 215'. Pulled DP, set bridge @ ho! with \$200 Sx. RECEIVED STATE CORPORATION COMMISSION I hereby certify that the 3507'2 Weld6gas plugged as herein stared. RECEIVED CONSERVATION DIVISION Signed:	Complete Address	1130 Wichita Plaza	ι Building, Wi	ichita, Ka	nsas.	
Abandoned Oil Well Gas Well Input Well SWD Well D&A X Other well as hereafter indicated Plugging Contractor Abercrombie Drilling, Incorporated, Address 801 Union Center Building, Wichita, Kansas. License No. Operation Completed: Hour 7:00 AM Day 16 Month 7 Year 1969 The above well was plugged as follows: 261'8 5/8" Surface casing, cement circulated with 200 Sx. Top of Dakota section @ 1800'. Circulated hole with heavy mud. Pulled DP to 2000'and displaced 100 Sx. cement the DP from 2000' to 1675'. Pulled DP to 275' and displaced 20 Sx. cement thru DP from 275' to 215'. Pulled DP, set bridge @ h0' with \$\frac{1}{2}\$ sack hulls and 10 Sx. cement to bottom of cellar. RECEIVED STATE CORPORATION COMMISSION CONSERVATION DIVISION Signed:	Lease Name	Charles	1	Well No.	2	
Abandoned 011 Well Gas Well Input Well SWD Well D&A X Other well as hereafter indicated Plugging Contractor Abercrombie Drilling, Incorporated, Address 801 Union Center Building, Wichita, Kansas. License No. Operation Completed: Hour 7:00 AM Day 16 Month 7 Year 1969 The above well was plugged as follows: 261'-8 5/8" Surface casing, cement circulated with 200 Sx. Top of Dakota section @ 1800'. Circulated hole with heavy mud. Pulled DP to 2000'and displaced 100 Sx. cement the DP from 2000' to 1675'. Pulled DP to 275' and displaced 20 Sx. cement thru DP from 275' to 215'. Pulled DP, set bridge @ ho' with \(\frac{1}{2} \) sack hulls and 10 Sx. cement to bottom of cellar. RECEIVED STATE CORPORATION COMMISSION RECEIVED CONSERVATION DIVISION Signed:	Location	$\overline{\mathrm{CMF}}_{\mathrm{ann}}$ $\overline{\mathrm{ME}}_{\mathrm{constitute}}$	Sec.	29 Twp. 3	Rge	(E)(W)_
Abandoned Oil Well Gas Well Input Well SWD Well D&A X Other well as hereafter indicated Plugging Contractor Abercrombie Drilling, Incorporated, Address 801 Union Center Building, Wichita, Kansas. License No. Operation Completed: Hour 7:00 AM Day 16 Month 7 Year 1969 The above well was plugged as follows: 261'-8 5/8" Surface casing, cement circulated with 200 Sx. Top of Dakota section @ 1800'. Circulated hole with heavy mud. Pulled DP to 2000'and displaced 100 Sx. cement the DP from 2000' to 1675'. Pulled DP to 275' and displaced 20 Sx. cement thru DP from 275' to 215'. Pulled DP, set bridge @ h0' with \$\frac{1}{2}\$ sack hulls and 10 Sx. cement to bottom of cellar. RECEIVED STATE CORPORATION COMMISSION RECEIVED CONSERVATION DIVISION Signed:	County (September 1981)	Decatur		Total D	epth	3956 1
Plugging Contractor Abercrombie Drilling, Incorporated, Address 801 Union Center Building, Wichita, Kansas. License No. Operation Completed: Hour 7:00 AM Day 16 Month 7 Year 1969 The above well was plugged as follows: 261'-8 5/8" Surface casing, cement circulated with 200 Sx. Top of Dakota section @ 1800'. Circulated hole with heavy mud. Pulled DP to 2000'and displaced 100 Sx. cement the DP from 2000' to 1675'. Pulled DP to 275' and displaced 20 Sx. cement thru DP from 275' to 215'. Pulled DP, set bridge @ ho! with \(\frac{1}{2} \) sack hulls and 10 Sx. cement to bottom of cellar. RECEIVED STATE CORPORATION COMMISSION hereby certify that the 300'2 % 196 gas plugged as herein stated. CONSERVATION DIVISION Signed:						
Plugging Contractor Abercrombie Drilling, Incorporated, Address 801 Union Center Building, Wichita, Kansas. License No. Operation Completed: Hour 7:00 AM Day 16 Month 7 Year 1969 The above well was plugged as follows: 261!8 5/8" Surface casing, cement circulated with 200 Sx. Top of Dakota section @ 1800". Circulated hole with heavy mud. Pulled DP to 2000 and displaced 100 Sx. cement the DP from 2000 to 1675. Pulled DP to 275 and displaced 20 Sx. cement thru DP from 275 to 215. Pulled DP, set bridge @ ho! with \$ sack hulls and 10 Sx. cement to bottom of cellar. RECEIVED STATE CORPORATION COMMISSION NVOICED CONSERVATION DIVISION Signed:	Other well as herea:	fter indicated				,
Pheration Completed: Hour 7:00 AM Day 16 Month 7 Year 1969 The above well was plugged as follows: 261'8 5/8" Surface casing, cement circulated with 200 Sx. Top of Dakota section @ 1800'. Circulated hole with heavy mud. Pulled DP to 2000'and displaced 100 Sx. cement the DP from 2000' to 1675'. Pulled DP to 275' and displaced 20 Sx. cement thru DP from 275' to 215'. Pulled DP, set bridge @ ho! with \$\frac{1}{2}\$ sack hulls and 10 Sx. cement to bottom of cellar. RECEIVED STATE CORPORATION COMMISSION hereby certify that the \$\frac{1}{2}\text{Poptog} 2\text{966gas plugged as herein started.} CONSERVATION DIVISION Signed:						
Operation Completed: Hour 7:00 AM Day 16 Month 7 Year 1969 The above well was plugged as follows: 261'8 5/8" Surface casing, cement circulated with 200 Sx. Top of Dakota section @ 1800'. Circulated hole with heavy mud. Pulled DP to 2000' and displaced 100 Sx. cement the DP from 2000' to 1675'. Pulled DP to 275' and displaced 20 Sx. cement thru DP from 275' to 215'. Pulled DP, set bridge @ ho! with ½ sack hulls and 10 Sx. cement to bottom of cellar. RECEIVED STATE CORPORATION COMMISSION Never by Certify that the 300' 2 36' 166 gas plugged as herein started. CONSERVATION DIVISION Signed:	•			3	The state of the s	
The above well was plugged as follows: 261'8 5/8" Surface casing, cement circulated with 200 Sx. Top of Dakota section @ 1800'. Circulated hole with heavy mud. Pulled DP to 2000'and displaced 100 Sx. cement the DP from 2000' to 1675'. Pulled DP to 275' and displaced 20 Sx. cement thru DP from 275' to 215'. Pulled DP, set bridge @ 40' with \(\frac{1}{2} \) sack hulls and 10 Sx. cement to bottom of cellar. RECEIVED STATE CORPORATION COMMISSION hereby certify that the above 2 196 gas plugged as herein stared. CONSERVATION DIVISION Signed:						
RECEIVED STATE CORPORATION COMMISSION Thereby certify that the 900v2 3666 gas plugged as herein stated. CONSERVATION DIVISION Wightin Korres Signed:	Circulated hole wit	h heavy mud. Pulled	DP to 200 0 an	d displa c e	d 100 Ss	
RECEIVED STATE CORPORATION COMMISSION Thereby certify that the apprentiation plugged as herein stated. CONSERVATION DIVISION Signed:						
RECEIVED STATE CORPORATION COMMISSION Nereby certify that the 300ve 366 gas plugged as herein stated. CONSERVATION DIVISION Signed:	DP from 2000: to 16	751. Pulled DP to 279	5' and displa	ced 20 Sx.	cement	thru DP from
STATE CORPORATION COMMISSION Nereby certify that the 300ve 366 gas plugged as herein stated. CONSERVATION DIVISION Signed:	DP from 2000; to 16	751. Pulled DP to 271	5' and displa	ced 20 Sx. k hulls an	cement	thru DP from
STATE CORPORATION COMMISSION Nereby certify that the 300ve weld 6 gas plugged as herein stated. CONSERVATION DIVISION Signed:	DP from 2000; to 16	751. Pulled DP to 271	5' and displa	ced 20 Sx. k hulls an	cement	thru DP from
CONSERVATION DIVISION Signed:	DP from 2000: to 16	75'. Pulled DP to 27' ed DP, set bridge @ 40	5° and displa 0° with ½ sac	ced 20 Sx. k hulls an	cement	thru DP from
Signed:	DP from 2000: to 16	751. Pulled DP to 279 ed DP, set bridge @ 140 RECEIVED STATE CORPORATION COMMISSIO	5' and displa O' with 를 sac	ced 20 Sx.	cement d 10 Sx.	thru DP from
	DP from 2000: to 16	RECEIVED STATE CORPORATION COMMISSION t the 3000234669as 1	5° and displa O' With ½ sac	ced 20 Sx.k hulls an	cement d 10 Sx.	thru DP from