4- <u>071102</u>	2 7-14
TO: STATE CORPORATION COMMISSION CONSERVATION DIVISION - PLUGGING 200 COLORADO DERBY BUILDING WICHITA, KANSAS 67202	API number: 15-147-20,558-00-00  NW NW SW /4 SEC. 18 , 04 S, 18 W 2310
Operator license#_5011	Lease Shaw well # 1
Operator: Viking Resources, Inc.	County Phillips
Address: <u>105 S. Broadway - #1040</u> <u>Wichita, Kansas 67202</u>	1/1.64/
Aband. oil well, Gas well, Inp	out well, SWD, D & A _x_
Plugging contractor: Murfin Drilling C	ompany License# 30606
Address: Wichita, Kansas 67202	
Company to plug at: Hour: A.M. Day: 14 Month: July Year: 94	
Plugging proposal received from: <u>Keith Vanpelt</u>	
Company: Murfin Drilling Company Phone: 316-262-2502	
Were: 8 5/8" - 212' cwc. w/140 sxs. 60/40 pozmix - 3% c.c 2% qel.  By Allied Cement. K.C. well - Elv. 1967' - Anhy. 1525' - No circulation  problems - Mud condition 58 vis 9.2 wt 8 water loss - 1100 ppm cl.  at T.D. Proposal 190 sxs. 60/40 pozmix - 6% gel - 1 sx. flocele.  Circulate hole - 42-45 vis.mud. Spot and displace all cement through  drill stem - heavy mud between all plugs. 25 sxs. @ 1530' - 100 sxs. with  1 sx. flocele @ 900' - 40 sxs. @ 260' - 10 sxs. @ 40' - 15 sxs. in rathole.	
Plugging Proposal Received by: Marion	J. Schmidt (circulate)
Plugging operations attended by agent?	_
Completed: Hour: 11:45A.M, Day: 14, Mon	nth: <u>July</u> , Year: <u>94</u>
Actual plugging report: Murfin ordered 1 sx. flocele. Circulated hole - spott through drill pipe. Heavy mud between 1st. plug at 1530' w/25 sxs. cement.  2nd. plug at 900' w/100 sxs. cement w/3rd. plug at 260' w/40 sxs. cement.  4th. plug at 40' w/10 sxs. cement.  15 sxs. in rathole (circulated)	d 190 sxs. 60/40 poazmix - 6% gel - ted and displaced all cement all plugs.  /1 sx. flocele.  STATE COLOR 1994  JUL-19 DIVISION
Actual plugging report: Murfin ordered 1 sx. flocele. Circulated hole - spott through drill pipe. Heavy mud between 1st. plug at 1530' w/25 sxs. cement.  2nd. plug at 900' w/100 sxs. cement w/3rd. plug at 260' w/40 sxs. cement.  4th. plug at 40' w/10 sxs. cement.  15 sxs. in rathole (circulated)  Remarks: Cemented by: Allied Cement Condition of casing(in hole):GOOD BABOTTOM Plugged through TUBING X , CASING	d 190 sxs. 60/40 poazmix - 6% gel - ted and displaced all cement all plugs.  /1 sx. flocele.  STATE CONSTRUCT COMMISSION  ADAnhy.plug:YESX_NO
through drill pipe. Heavy mud between  1st. plug at 1530' w/25 sxs. cement.  2nd. plug at 900' w/100 sxs. cement w/  3rd. plug at 260' w/40 sxs. cement.  4th. plug at 40' w/10 sxs. cement.  15 sxs. in rathole (circulated)  Remarks:Cemented by: Allied Cement Condition of casing(in hole):GOODBA  Bottom plug(in place):YES,CALC_  Plugged through TUBINGX, CASING  I did [ V ] O did root [ X ] observe the pl	d 190 sxs. 60/40 poazmix - 6% gel - ted and displaced all cement all plugs.  /1 sx. flocele.  STATE PORPODE THE COMMISSION  CONSTRUCTION DIVISION  CONSTRUCTION DIVISION  L. ADAnhy.plug:YESX_NO,NODakota plug:YESX_,NO Elevation: 1967 GL  Lugging.  Lugging.
through drill pipe. Heavy mud between  1st. plug at 1530' w/25 sxs. cement.  2nd. plug at 900' w/100 sxs. cement w/  3rd. plug at 260' w/40 sxs. cement.  4th. plug at 40' w/10 sxs. cement.  15 sxs. in rathole (circulated)  Remarks:Cemented by: Allied Cement Condition of casing(in hole):GOODBR Bottom plug(in place):YES,CALC_ Plugged through TUBINGX, CASING	d 190 sxs. 60/40 poazmix - 6% gel - ted and displaced all cement all plugs.  /1 sx. flocele.  STATE CONSTRUCTION DIVISION  CONSTRUCTION DIVISION  CONSTRUCTION DIVISION  ADAnhy.plug:YESX_NO,NODakota plug:YES_X_,NO Elevation: 1967 GL