

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission Conservation Division 800 Bitting Building Wichita, Kansas

800 Bitting Building Wichita, Kansas	4
with the state of	FILE NO. CSL nul
	LOCATION CS-NW/L
•	SEC. 10 TWP. 5 RGE. 10W
Dry Hole *** Abandoned Cil Well	Abandoned Gas Well
I have today completed supervision of pluggi	ing of:
Well No. 1 Lease Beard	
Operator Louis M. Mai. Add	ress Russell, Kansas.
Operator Louis M. Mai. Add Field Cou	inty Jewell William
motol Donth 271Eft most	and the state of t
Plugging Contractor. Louis M. Mai Plugging Contractor's License No Address Russell, Kansas.	the well was plugged 9-17-56
Surface pipe - None. 8 5/8" @ 2	5 <u>1.0:, 10"@815:, 12 </u>
	ipe, when free, stopped and filled hole
with heavy mud. (Had Halliburton Pump Truck to jet up pond to get heavy	
mud and pump into the hole). After 8 5/8" pipe was out, the same	
procedure with the 10" & 121" pipe.	
it up to 270! from top, set plug, ro	
	pipe out and mud to 35' from top, set
plug, rock bridge and 20 sx. cem.	Wilton Sals alt.
to base of cellar.	District Conservation Agent
(Halliburton was used for mud & cem.	PLUGGING FILE SEC 10 T S R 10W BOOK FRAGE 99 LINE 31