15-147-19111-00-00

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission Conservation Division 8CO Bitting Building Wichita, Kansas

800 Bitting Building	
Wichita, Kansas	·
	FILE NO. 44-1
•	LOCATION CSW NE NE
	SEC. 14 TWP. 5 RGE. 20
Dry Hole X Abandoned Oil Well	Abandoned Gas Well
I have today completed supervision of pla	agging of:
Well No. 1 Lease Rundle	Box 186
Operator Cities Service Co Address	ess Great Bend, Kans
Field Count	
Total Depth 3465 Feet.	, , , , , , , , , , , , , , , , , , , ,
(Describe briefly the manner in white 8 5/8" at 207' circulated with ce	
behind. Top cement in $5\frac{1}{2}$ 3432.	top perforations at 3246',
Filled with sand to 3240', set 4	sax cement with dump bailer,
pulled 2010' 52", filled hole wit	h mud to 200', set rock bridge
and 15 sax cement, filled with mu	d to 351, set rock bridge and
10 sax cement to bottom cellar	handinandiyanin dan ankandan ahada giranya dan ayan dagaa aya baran ahaa asaa asaa asaa asaa ahaa da ahaa da a
	ana ang ang ang ang ang ang ang ang ang
	DEC 8 1950 RISSION
PLUGGING _	District Conservation Ment
BOOK PACK-MANAGEMENT DE	ate 12-9-50 /2-/8-S
ment depends a service and the control of the contr	and the state of t