15.207.19461.0000

3 022671

To:	API NUMBER	CONTROL NO. 20040041		
STATE CORPORATION COMMISSION	NW,NE,SW 1/4	Sec/Twp/Rge	S.34-T.265	SR.16E
chita State Office Bldg PLUGGING SECTION feet from south section line				
130 S. Market, Room 2078 Wichita, Kansas 67202	3700	feet from eas	st section lir	ne
TECHNICIAN'S PLUGGING REPORT	Lease/Well#	APT NO. 74		
Operator License # D	County	WOODSON		
Operator: STATE OF KANSAS Fee Fund	Well Total Depth	1000'		feet
Name & FEE FUND PLUGGING	Production Pipe:	-	Size Feet	
Address	Surface Casing:	8"	Size Feet	20'
AB oil well X Gas Well SWD Well	/ Input Well		D & A	
Other well as hereinafter indicated:	-			
Plugging Contractor: SPLANE PULLING AND ROUST.	ABOUT SERVICE		Lic.#	6372
Address: BOX 386, RR4, CHANUTE, KANSAS 66720	- ~			
Company to plug at: Hour: 9:00A.M. Day:	14	Month:	12	2004
Plugging proposal received from: CLAYTON P. TITEL	The second control of	****		-
Company Name: KANSAS CORPORATION COMM	MISSION	Phone:	620-432-23	300
Were: THIS WAS AN OLD WELL ABOUT WHICH N	NOTHING IS KNO	WN. THE PLU	JGGING	Res
PROPOSAL WAS TO DRILL OUT THE WELL AND TO	CIRCULATE AS M	IUCH OF TH	WELL	DECEIVE
AS POSSIBLE FULL OF CEMENT.				CC WICHITA
		3	9	CCWC
Plugging Proposal Re	ceived by:	CLAYTON P	. TITEL	MITA
Plugging attended by Agent: All X	_Part		None None	
Operations Completed: Hour: 12:00P.M. Day:	14	Month:	12	2004
Actual Plugging Report: THE WELL WAS DRILLED OUT TO 500'. AT THAT DEPTH				
IDONIANA CENCOLINITEDED AUDIDE MAS DANIAS			*	
IRON WAS ENCOUNTERED. 1" PIPE WAS RAN INTO	THE WELL TO 50	D'. CEMENT	WAS	
PUMPED INTO THE 1" PIPE UNTIL CEMENT CIRCULA				
PUMPED INTO THE 1" PIPE UNTIL CEMENT CIRCULA	ATED FROM THE	SURFACE C	ASING	
PUMPED INTO THE 1" PIPE UNTIL CEMENT CIRCULA	ATED FROM THE	SURFACE C	ASING	
PUMPED INTO THE 1" PIPE UNTIL CEMENT CIRCULA AT SURFACE. THE 1" PIPE WAS REMOVED. 195 SAC	ATED FROM THE	SURFACE C	ASING	
PUMPED INTO THE 1" PIPE UNTIL CEMENT CIRCULA AT SURFACE. THE 1" PIPE WAS REMOVED. 195 SAC	ATED FROM THE	SURFACE C	ASING	
PUMPED INTO THE 1" PIPE UNTIL CEMENT CIRCULA AT SURFACE. THE 1" PIPE WAS REMOVED. 195 SAC	ATED FROM THE KS OF CEMENT \ VAS WAS NOT SH	SURFACE C	ASING ED	MAP.)

Signed:

TECHNICIAN

