3 022687

15-207-19470.0000

	API NUMBER	001111102	NO. 200400	T 1
STATE CORPORATION COMMISSION	SE,NW,SW 1/4	_Sec/Twp/Rge	vp/Rge <u>S.34-T.26SR.16E.</u>	
Wichita State Office Bldg PLUGGING SECTION	1446	feet from so	uth section I	ine
130 S. Market, Room 2078 Wichita, Kansas 67202	4572	e feet from ea	st section lir	ne
TECHNICIAN'S PLUGGING REPORT	Lease/Well#	Lease/Well# APT NO. 19		
Operator License # 101	County	WOODSON		
Operator: STATE OF KANSAS Fee Fund	Well Total Depth	1000'	,	feet
Name & FEE FUND PLUGGING	Production Pipe:	4 1/2"	_Size Feet	1000'
Address	Surface Casing:	7	_Size Feet	20'
AB oil well X Gas Well SWD W	ell/ Input Well	Mustbergung and and an artistation	_D & A	
Other well as hereinafter indicated:				
Plugging Contractor: SPLANE PULLING AND ROUS	STABOUT SERVICE		_Lic.#	6372
Address: BOX 386, RR4, CHANUTE, KANSAS 667	20			
Company to plug at: Hour: 12:00P.M. Day:	27	Month:	1	2005
Plugging proposal received from: CLAYTON P. TITE	<u> </u>			
Company Name: KANSAS CORPORATION CO	MMISSION	_Phone:	620-432-23	300
Were: THIS WELL CONSISTED OF 4 1/2" CASI	NG TO APPROXIMA	TELY 1000'	THAT HAD	****
BEEN CEMENTED IN FROM BOTTOM TO TOP. THI	E PLUGGING PROP	OSAL WAS	го	
CIRCULATE THE 4 1/2" CASING FULL OF CEMENT				
CIRCULATE THE 4 1/2" CASING FULL OF CEMENT				***************************************
CIRCULATE THE 4 1/2" CASING FULL OF CEMENT Plugging Proposal		CLAYTON	P. TITEL	
Plugging Proposal	Received by:	CLAYTON	TECHNICIAN	
Plugging Proposal Plugging attended by Agent: All	Received by:Part			<u>X</u>
Plugging Proposal Plugging attended by Agent: All Operations Completed: Hour: 4:00P.M. Day:	Received by:Part27	Month:	TECHNICIAN None 1	X 2005
Plugging Proposal Plugging attended by Agent: All Operations Completed: Hour: 4:00P.M. Day: Actual Plugging Report: 1" PIPE WAS RAN	Received by:Part27 INTO THE 4 1/2" CA	Month:	TECHNICIAN _None1 5'. CEMENT	X 2005
Plugging Proposal Plugging attended by Agent: All Operations Completed: Hour: 4:00P.M. Day: Actual Plugging Report: 1" PIPE WAS RAN WAS PUMPED INTO THE 1" PIPE UNTIL CEMENT	Received by:Part27 INTO THE 4 1/2" CA	Month: ASING TO 92 THE 4 1/2" C	TECHNICIAN _None1 5'. CEMENT	X 2005
Plugging Proposal Plugging attended by Agent: All Operations Completed: Hour: 4:00P.M. Day: Actual Plugging Report: 1" PIPE WAS RAN WAS PUMPED INTO THE 1" PIPE UNTIL CEMENT SURFACE. THE 1" PIPE WAS REMOVED. DISPLAC	Received by: Part 27 INTO THE 4 1/2" CA CIRULATED FROM EMENT WAS FILLE	Month: ASING TO 92 THE 4 1/2" C	TECHNICIAN None 1 5'. CEMENT ASING AT RFACE.	X 2005
Plugging Proposal Plugging attended by Agent: All Operations Completed: Hour: 4:00P.M. Day: Actual Plugging Report: 1" PIPE WAS RAN WAS PUMPED INTO THE 1" PIPE UNTIL CEMENT	Received by: Part 27 INTO THE 4 1/2" CA CIRULATED FROM EMENT WAS FILLE	Month: ASING TO 92 THE 4 1/2" C	TECHNICIAN None 1 5'. CEMENT ASING AT RFACE.	2005 CEIVED
Plugging Proposal Plugging attended by Agent: All Operations Completed: Hour: 4:00P.M. Day: Actual Plugging Report: 1" PIPE WAS RAN WAS PUMPED INTO THE 1" PIPE UNTIL CEMENT SURFACE. THE 1" PIPE WAS REMOVED. DISPLAC	Received by: Part 27 INTO THE 4 1/2" CA CIRULATED FROM EMENT WAS FILLE	Month: ASING TO 92 THE 4 1/2" C	TECHNICIAN None 1 5'. CEMENT ASING AT RFACE. RE	2005 CEIVED B 0 9 2005
Plugging Proposal Plugging attended by Agent: All Operations Completed: Hour: 4:00P.M. Day: Actual Plugging Report: 1" PIPE WAS RAN WAS PUMPED INTO THE 1" PIPE UNTIL CEMENT SURFACE. THE 1" PIPE WAS REMOVED. DISPLAC	Received by: Part 27 INTO THE 4 1/2" CA CIRULATED FROM EMENT WAS FILLE	Month: ASING TO 92 THE 4 1/2" C	TECHNICIAN None 1 5'. CEMENT ASING AT RFACE. RE	2005 CEIVED
Plugging Proposal Plugging attended by Agent: All Operations Completed: Hour: 4:00P.M. Day: Actual Plugging Report: 1" PIPE WAS RAN WAS PUMPED INTO THE 1" PIPE UNTIL CEMENT SURFACE. THE 1" PIPE WAS REMOVED. DISPLAC	Received by: Part 27 INTO THE 4 1/2" CA CIRULATED FROM EMENT WAS FILLE S WELL. L WAS NOT ILLUS	Month: ASING TO 92 THE 4 1/2" C	TECHNICIAN None 1 5'. CEMENT ASING AT REACE. RE	X 2005 CEIVED B 0 9 2005 CWICHIT
Plugging Proposal Plugging attended by Agent: All Operations Completed: Hour: 4:00P.M. Day: Actual Plugging Report: 1" PIPE WAS RAN WAS PUMPED INTO THE 1" PIPE UNTIL CEMENT SURFACE. THE 1" PIPE WAS REMOVED. DISPLAC 86 SACKS OF CEMENT WERE PUMPED INTO THIS Remarks: (GPS SESSION PT. NO. 19) (THIS WEL	Received by: Part 27 INTO THE 4 1/2" CA CIRULATED FROM EMENT WAS FILLE S WELL. L WAS NOT ILLUS	Month: ASING TO 92 THE 4 1/2" C	TECHNICIAN None 1 5'. CEMENT ASING AT REACE. RE	X 2005 CEIVED B 0 9 2005 CWICHIT

0...