15.207.19521-00-0

To:	API NUMBER	CONTROL NO. 20040041			
STATE CORPORATION COMMISSION	NE,SE,SW 1/4	Sec/Twp/Rge	S.34-T.265	6R.16E.	
Wichita State Office Bldg PLUGGING SECTION	1187	feet from south section line			
130 S. Market, Room 2078 Wichita, Kansas 67202	2900	feet from eas	st section lir	ne	
TECHNICIAN'S PLUGGING REPORT	Lease/Well#	APT NO. 84		Jun	
Operator License #	County	WOODSON			
Operator: STATE OF KANSAS Fee Fund	Well Total Depth	1000'		feet	
Name & FEE FUND PLUGGING	Production Pipe:	V	Size Feet		
Address	Surface Casing:	8"	Size Feet	20'	
AB oil well X Gas Well SWD Well	/ Input Well		D&A	« pro-	
Other well as hereinafter indicated:					-
Plugging Contractor: SPLANE PULLING AND ROUST.	ABOUT SERVICE		Lic.#	63	<u>72</u>
Address: BOX 386, RR4, CHANUTE, KANSAS 66720					
Company to plug at: Hour: 10:00AM Day:	5	Month:	12	_ 20	05
Plugging proposal received from: CLAYTON P. TITEL					
Company Name: KANSAS CORPORATION COMM	MISSION	Phone:	620-432-23	300	
Were: VISIBLE AT SURFACE ON THIS WELL WAS	S 8" SURFACE CA	SING ONLY			
THE PLUGGING PROPOSAL WAS TO CIRCULATE AS	MUCH OF THE V	VELL AS PO	SSIBLE		
FULL OF CEMENT.					
Plugging Proposal Re	ceived by:	CLAYTON F	P. TITEL		
Plugging attended by Agent: All	_Part		TECHNICIAN None	X	
Operations Completed: Hours 1:00DM Days					
Operations Completed: Hour: 1:00PM Day:	5	Month:	12		05
Actual Plugging Report: Additional Completed: Hour: A 4" SWEDGE WAS I		-			05
	RAN INTO THE W	- ELL TO 200'	WITHOUT		05 —
Actual Plugging Report: A 4" SWEDGE WAS I	RAN INTO THE W	- ELL TO 200' 1" PIPE WAS	WITHOUT S RAN		05 — —
Actual Plugging Report: A 4" SWEDGE WAS I ENCOUNTERING AN OBSTRUCTION. THE SWEDGE	RAN INTO THE W WAS REMOVED. DBSTRUCTION WA	- ELL TO 200' 1" PIPE WAS AS ENCOUN	WITHOUT S RAN TERED.		05 — —
Actual Plugging Report: A 4" SWEDGE WAS I ENCOUNTERING AN OBSTRUCTION. THE SWEDGE INTO THE WELL TO 425'. AT THAT DEPTH A SOLID O	RAN INTO THE W WAS REMOVED. DBSTRUCTION WA	- ELL TO 200' 1" PIPE WAS AS ENCOUN ED FROM TH	WITHOUT S RAN TERED. HE		05 —— ——
Actual Plugging Report: A 4" SWEDGE WAS I ENCOUNTERING AN OBSTRUCTION. THE SWEDGE INTO THE WELL TO 425'. AT THAT DEPTH A SOLID C CEMENT WAS PUMPED INTO THE 1" PIPE UNTIL CE	RAN INTO THE W WAS REMOVED. DESTRUCTION WAS MENT CIRCULAT REMOVED. DISPL	ELL TO 200' 1" PIPE WAS AS ENCOUN ED FROM TH	WITHOUT S RAN TERED. HE		05 —— —— ——
Actual Plugging Report: A 4" SWEDGE WAS I ENCOUNTERING AN OBSTRUCTION. THE SWEDGE INTO THE WELL TO 425'. AT THAT DEPTH A SOLID C CEMENT WAS PUMPED INTO THE 1" PIPE UNTIL CE SURFACE CASING AT SURFACE. THE 1" PIPE WAS I	RAN INTO THE W WAS REMOVED. DESTRUCTION WAS MENT CIRCULAT REMOVED. DISPL	ELL TO 200' 1" PIPE WAS AS ENCOUN ED FROM TH	WITHOUT S RAN TERED. HE	20	
Actual Plugging Report: A 4" SWEDGE WAS I ENCOUNTERING AN OBSTRUCTION. THE SWEDGE INTO THE WELL TO 425'. AT THAT DEPTH A SOLID C CEMENT WAS PUMPED INTO THE 1" PIPE UNTIL CE SURFACE CASING AT SURFACE. THE 1" PIPE WAS I	RAN INTO THE W WAS REMOVED. DBSTRUCTION WAS MENT CIRCULAT REMOVED. DISPL RE PUMPED INTO	ELL TO 200' 1" PIPE WAS AS ENCOUN ED FROM TH ACEMENT V O THIS WELL	WITHOUT S RAN TERED. HE VAS	20	05

Signed:

Bry