| DISTRICT CONSERVATION AGENT'S REPORT  |              |
|---|--------------|
| TO:   | alegar South |
| State Corporation Commission Conservation Division 800 Ditting Building Wichita, Kansas | •            |
| FILE NO.  |              |
| LOCATION NW NW SE   | p            |
| SEC. 16 TWP. 7 RGE. 22  | U            |
| Dry Hole X Abandoned Cil Well Abandoned Gas Well  |              |
| I have today completed supervision of plugging of:                                      |              |
| Well No. B-l Lease Fabricus   | -            |
| Operator Murfin Drg Co Address Wichita, Kans  |              |
| FieldCounty_ Graham   | er, sek      |
| Total Depth 3860 Feet.  |              |
| (Describe briefly the manner in which the well was plugged)                             |              |
| 8 5/8" at 160' circulated with cement.  | ncina,       |
| Filled with mud to 155', set cementing plug, 1/2 sack hulls                             | ****         |
| and 15 sax cement, mud to 40', set cementing plug, 1/2 sack                             | ca.          |
| hulls and 10 sax cement to bottom cellar.   |              |
|   | _            |
|   | _            |
|   | _            |
|   | -            |
|   | •            |
| STATE CONTROL CONTROL District Conservation Ager  |              |
| District Conservation Ager  | īt           |

Wichia, Langa Pivision