4-090513

CONSERVATION DIVISION - PLUGGING	TO:	API number: 15-193-20,614	
2310 feet from S section line WICHTTA, KANSAS 67202 Departor: Itense# 5131 Operator: Thunderbird Drilling, Inc. Ocunty Thomas Address: P.O. Box 780407 Wichita, Kansas 67278 Operator: Thunderbird Drilling, Inc. Ocupang & 5/8 Inch @ O feet Surface pipe 8 5/8 Inch @ O	STATE CORPORATION COMMISSION	NE NE CE // CEC 20 OF C 21 W	
Operator license# 5131 Decay Ret from E section line Operator: Thunderbird Drilling, Inc. County Thomas Address: P.O. Box 780407 Well total depth 4580 feet Surface pipe 8 5/8 Inch @ 263 feet Aband. oil well _, Gas well _, Input well _, SWD _, D & A X Plugging contractor: Abercrombie RTD, Inc. License#30684 Address: Wichita, Kansas 67202 Company to plug at: Hour: P.M. Day: 3 Month: December Year: 93 Plugging proposal received from: Gary Fisher Company: Abercrombie RTD, Inc. Phone: Were: Order 190 sxs. 60/40 posmix with 6% gel and 1 sx. celloflake. Spot all plugs through drill pipe with heavy mud between all plugs. Plugging proposal Received by: Ed Schumacher Plugging operations attended by agent? All[], Part[], None[X] Completed: Hour: 7:15A.M., Day: 7 , Month: December , Year: 93 Actual plugging report: lst. plug at 2670! w/25 sxs. 2nd. plug at 315! w/40 sxs. 4th. plug at 315! w/40 sxs. 4th. plug at 40! w/10 sxs. 15 sxs. in rathole. RECEIVED REMERATION DUNISON CONSERVATION DUNISON CONSERVATI	200 COLODADO DEDRY RITLDING	2310 feet from S section line	
Operator license# 5131 Departor: Thunderbird Drilling, Inc. County Thomas Address: P.O. Box 780407 Wichita, Kansas 67278 Conductor Pipe: 0 inch 0 of feet Surface pipe 8 5/8 Inch 0 253 feet Aband. oil well, Gas well, Input well, SWD, D & A _X Plugging contractor: Abergrombie RTD, Inc License#30684 Address: Wichita, Kansas 67202 Company to plug at: Hour: P.M. Day: 3 Month: December Year: 93 Plugging proposal received from: Gary Fisher Company: Abergrombie RTD, Inc Phone:			
Operator: Thunderbird Drilling, Inc. County Thomas Address: P.O. Box 780407 Wichita, Kansas 67278 Conductor Pipe: 0 inch 0 0 feet Surface pipe 8 5/8 Inch 0 263 feet Aband. oil well, Gas well, Input well, SWD, D & A _X Plugging contractor: Abercrombie RTD, Inc. License 30684 Address: Wichita, Kansas 67202 Company to plug at: Hour: P.M. Day: 3 Month: December Year: 93 Plugging proposal received from: Gary Fisher Company: Abercrombie RTD, Inc. Phone: Were: Order 190 sxs. 60/40 posmix with 6% gel and 1 sx. celloflake. Spot all plugs through drill pipe with heavy mud between all plugs. Plugging Proposal Received by: Ed Schumacher Plugging operations attended by agent? All[], Part[], None[X] Completed: Hour:7:15A.M., Day: 7 , Month: December , Year: 93 Actual plugging report: 1st. plug at 26701 w/25 sxs. 2nd. plug at 18301 w/100 sxs. 3rd. plug at 1830 w/100 sxs. 3rd. plug at 315 w/40 sxs. 4th. plug at 400 w/10 sxs. 15 sxs. in rathole. Remarks: By: Allied Cementing. No arbuckle. Remarks: By: Allied Cementing. No arbuckle. Condition of casing(in hole):GOOD BAD Anhy. plug:YES NO SONSERWATION DIWISION CONSERWATION DIWISION CONSERVATION DIVISION	WICHITA, IMMORD 07202		
Operator: Thunderbird Drilling, Inc. County Thomas Address: P.O. Box 780407 Wichita, Kansas 67278 Conductor Pipe: 0 inch 0 0 feet Surface pipe 8 5/8 Inch 0 263 feet Aband. oil well, Gas well, Input well, SWD, D & A _X Plugging contractor: Abercrombie RTD, Inc. Company to plug at: Hour: P.M. Day: 3 Month: December Year: 93 Plugging proposal received from: Gary Fisher Company: Abercrombie RTD, Inc. Phone: Were: Order 190 sxs. 60/40 posmix with 6% gel and 1 sx. celloflake. Spot all plugs through drill pipe with heavy mud between all plugs. Plugging Proposal Received by: Ed Schumacher Plugging operations attended by agent? All[], Part[], None[X] Completed: Hour:7:15A.M., Day: 7 , Month: December , Year: 93 Actual plugging report: 1st. plug at 1830 w/100 sxs. 3rd. plug at 40 w/10 sxs. 4th. plug at 40 w/10 w/10 sxs. 4th. plug at 40 w/10 w/10 w/10 w/10 w/10 w/10 w/10 w/1	Operator license# 5131	Lease Keller Trust well # 1	
Aband. oil well, Gas well, Input well, SWD, D & A _X Plugging contractor: Abercrombie RTD, Inc.			
Aband. oil well, Gas well, Input well, SWD, D & A _X Plugging contractor: Abercrombie RTD, Inc.	Operator: Thunderbird Drilling, Inc.	County <u>rnomas</u>	
Aband. oil well, Gas well, Input well, SWD, D & A _X Plugging contractor: Abercrombie RTD, Inc.	Address: P.O. Box 780407	Well total depth 4580 feet	
Aband. oil well, Gas well, Input well, SWD, D & A _X Plugging contractor: Abercrombie RTD, Inc.	Wichita, Kansas 67278	Conductor Pipe: 0 inch @ 0 feet	
Plugging contractor: Abercrombie RTD, Inc. Address: Wichita, Kansas 67202 Company to plug at: Hour: P.M. Day: 3 Month: December Year: 93 Plugging proposal received from: Gary Fisher Company: Abercrombie RTD, Inc. Phone: Were: Order 190 sxs. 60/40 posmix with 6% gel and 1 sx. celloflake. Spot all plugs through drill pipe with heavy mud between all plugs. Plugging Proposal Received by: Ed Schumacher Plugging operations attended by agent? All[], Part[], None[X] Completed: Hour: 7:15A.M., Day: 7 , Month: December , Year: 93 Actual plugging report: 1st. plug at 2670' w/25 sxs. 2nd. plug at 1830' w/100 sxs. 3rd. plug at 315' w/40 sxs. 4th. plug at 40' w/10 sxs. 15 sxs. in rathole. RECEIVED STATE CAPOPURATION COMMISSION Condition of casing(in hole):GOOD BAD Anhy.plug:YES NO		Surface pipe 8 5/8 Inch @ <u>263</u> feet	
Address: Wichita, Kansas 67202 Company to plug at: Hour: P.M. Day: 3 Month: December Year: 93 Plugging proposal received from: Gary Fisher Company: Abercrombie RTD, Inc. Phone: Were: Order 190 sxs. 60/40 posmix with 6% gel and 1 sx. celloflake. Spot all plugs through drill pipe with heavy mud between all plugs. Plugging Proposal Received by: Ed Schumacher Plugging operations attended by agent? All[], Part[], None[X] Completed: Hour: 7:15A.M., Day: 7 , Month: December , Year: 93 Actual plugging report: 1st. plug at 2670! w/25 sxs. 2nd. plug at 1830! w/100 sxs. 3rd. plug at 1830! w/100 sxs. 3rd. plug at 315! w/40 sxs. 4th. plug at 40! w/10 sxs. 15 sxs. in rathole. RECEIVED Bottom plug(in place): YES , CALC , NO X Dakota plug: YES , NO EL 15 1993 Plugged through TUBING , CASING , Elevation: 2983 GL CONSERNATION DIVISION CONSERNATION DIVISION D	Aband. oil well, Gas well, Inp	ut well, SWD, D & A _X_	
Company to plug at: Hour: P.M. Day: 3 Month: December Year: 93 Plugging proposal received from: Gary Fisher Company: Abercrombie RTD, Inc. Phone: Were: Order 190 sxs. 60/40 posmix with 6% gel and 1 sx. celloflake. Spot all plugs through drill pipe with heavy mud between all plugs. Plugging Proposal Received by: Ed Schumacher Plugging operations attended by agent? All[], Part[], None[X] Completed: Hour: 7:15A.M., Day: 7 , Month: December , Year: 93 Actual plugging report: 1st. plug at 2670' w/25 sxs. 2nd. plug at 1830' w/100 sxs. 3rd. plug at 315' w/40 sxs. 3rd. plug at 315' w/40 sxs. 4th. plug at 40' w/10 sxs. 15 sxs. in rathole. Remarks: By: Allied Cementing. No arbuckle. STATE (PROPOSITION COMMANS) Condition of casing(in hole):GOOD BAD Anhy. plug: YES NO	Plugging contractor: Abercrombie RTD,	Inc. License#30684	
Plugging proposal received from: Gary Fisher Company: Abercrombie RTD, Inc. Phone: Were: Order 190 sxs. 60/40 posmix with 6% gel and 1 sx. celloflake. Spot all plugs through drill pipe with heavy mud between all plugs. Plugging Proposal Received by: Ed Schumacher Plugging operations attended by agent? All[], Part[], None[X] Completed: Hour: 7:15A.M., Day: 7 , Month: December , Year: 93 Actual plugging report: 1st. plug at 2670' w/25 sxs. 2nd. plug at 1830' w/100 sxs. 3rd. plug at 1830' w/100 sxs. 3rd. plug at 315' w/40 sxs. 4th. plug at 40' w/10 sxs. 15 sxs. in rathole. RECEIVED RECEIVED STATE CRESCOPATION COMMISS Condition of casing(in hole): GOOD BAD Anhy. plug: YES NO NO INC. 1 5 1993 Plugged through TUBING , CASING . Elevation: 2983 GL CONSERVATION DIVISION LANGE CONSERVATION DIVISION LANGE CONSERVATION DIVISION CONSERVATION DIVISION LANGE CONSERVATION DIVISION LANGE CONSERVATION DIVISION LANGE CONSERVATION DIVISION LANGE CONSERVATION DIVISION CONSERVATION DIVISION CONSERVATION DIVISION LANGE CONSERVATION DIVISION LANGE CONSERVATION DIVISION	Address: Wichita, Kansas 67202		
Company: Abercrombie RTD, Inc. Phone: Were:Order 190 sxs. 60/40 posmix with 6% gel and 1 sx. celloflake. Spot all plugs through drill pipe with heavy mud between all plugs. Plugging Proposal Received by:Ed Schumacher Plugging operations attended by agent? All[], Part[], None[X] Completed: Hour: 7:15A.M., Day: 7 , Month: _December	Company to plug at: Hour: P.M. Day:	3 Month: December Year: 93	
Were: Order 190 sxs. 60/40 posmix with 6% gel and 1 sx. celloflake. Spot all plugs through drill pipe with heavy mud between all plugs. Plugging Proposal Received by: Ed Schumacher Plugging operations attended by agent? All[], Part[], None[X] Completed: Hour: 7:15A.M., Day: 7 , Month: December , Year: 93 Actual plugging report: 1st. plug at 2670! w/25 sxs. 2nd. plug at 1830! w/100 sxs. 2nd. plug at 1830! w/100 sxs. 3rd. plug at 315! w/40 sxs. 4th. plug at 40! w/10 sxs. 15 sxs. in rathole. RECEIVED RECEIVED RECEIVED RECEIVED RECEIVED RECEIVED RECEIVED RECEIVED RECEIVED Remarks: By: Allied Cementing. No arbuckle. STATE COMPONDATION COMMISS Condition of casing(in hole):GOOD BAD Anhy.plug:YES NO DEC 15 1993 Plugged through TUBING , CASING . Elevation: 2983 GL CONSERVATION DINISION I did 10 1 Nif mgt[X] observe the plugging. Ed Achimacher in the conservation DINISION Lance 1 of 15 1993	Plugging proposal received from: Gary	Fisher	
Plugging Proposal Received by: Ed Schumacher Plugging operations attended by agent? All[], Part[], None[X] Completed: Hour:7:15A.M., Day: 7 , Month: December , Year: 93 Actual plugging report: 1st. plug at 2670' w/25 sxs. 2nd. plug at 1830' w/100 sxs. 3rd. plug at 315' w/40 sxs. 4th. plug at 40' w/10 sxs. 15 sxs. in rathole. Remarks: By: Allied Cementing. No arbuckle. Condition of casing(in hole):GOOD BAD Anhy.plug:YES NO Bottom plug(in place):YES , CALC , NO X Dakota plug:YES NO Plugged through TUBING , CASING . Elevation: 2983 GL I did [O 1 Ait 19t[X] observe the plugging.	Company: Abercrombie RTD, Inc.	Phone:	
Plugging operations attended by agent? All[], Part[], None[X] Completed: Hour:7:15A.M., Day: 7 , Month: December , Year: 93 Actual plugging report: 1st. plug at 2670' w/25 sxs. 2nd. plug at 1830' w/100 sxs. 3rd. plug at 315' w/40 sxs. 4th. plug at 40' w/10 sxs. 15 sxs. in rathole. RECEIVED Remarks: By: Allied Cementing. No arbuckle. Condition of casing(in hole):GOOD BAD Anhy.plug:YES NO DEC 15 1993 Plugged through TUBING , CASING . Elevation: 2983 GL CONSERVATION DIVISION I did [10 1	Were: Order 190 sxs. 60/40 posmix with 6% gel and 1 sx. celloflake. Spot all plugs through drill pipe with heavy mud between all plugs.		
Plugging operations attended by agent? All[], Part[], None[X] Completed: Hour:7:15A.M., Day: 7 , Month: December , Year: 93 Actual plugging report: 1st. plug at 2670' w/25 sxs. 2nd. plug at 1830' w/100 sxs. 3rd. plug at 315' w/40 sxs. 4th. plug at 40' w/10 sxs. 15 sxs. in rathole. RECEIVED Remarks: By: Allied Cementing. No arbuckle. Condition of casing(in hole):GOOD BAD Anhy.plug:YES NO DEC 15 1993 Plugged through TUBING , CASING . Elevation: 2983 GL CONSERVATION DIVISION I did [10 1			
Plugging operations attended by agent? All[], Part[], None[X] Completed: Hour:7:15A.M., Day: 7 , Month: December , Year: 93 Actual plugging report: 1st. plug at 2670' w/25 sxs. 2nd. plug at 1830' w/100 sxs. 3rd. plug at 315' w/40 sxs. 4th. plug at 40' w/10 sxs. 15 sxs. in rathole. RECEIVED Remarks: By: Allied Cementing. No arbuckle. Condition of casing(in hole):GOOD BAD Anhy.plug:YES NO DEC 15 1993 Plugged through TUBING , CASING . Elevation: 2983 GL CONSERVATION DIVISION I did [10 1			
Plugging operations attended by agent? All[], Part[], None[X] Completed: Hour:7:15A.M., Day: 7 , Month: December , Year: 93 Actual plugging report: 1st. plug at 2670' w/25 sxs. 2nd. plug at 1830' w/100 sxs. 3rd. plug at 315' w/40 sxs. 4th. plug at 40' w/10 sxs. 15 sxs. in rathole. RECEIVED Remarks: By: Allied Cementing. No arbuckle. Condition of casing(in hole):GOOD BAD Anhy.plug:YES NO DEC 15 1993 Plugged through TUBING , CASING . Elevation: 2983 GL CONSERVATION DIVISION I did [10 1			
Plugging operations attended by agent? All[], Part[], None[X] Completed: Hour:7:15A.M., Day: 7 , Month: December , Year: 93 Actual plugging report: 1st. plug at 2670' w/25 sxs. 2nd. plug at 1830' w/100 sxs. 3rd. plug at 315' w/40 sxs. 4th. plug at 40' w/10 sxs. 15 sxs. in rathole. RECEIVED Remarks: By: Allied Cementing. No arbuckle. Condition of casing(in hole):GOOD BAD Anhy.plug:YES NO DEC 15 1993 Plugged through TUBING , CASING . Elevation: 2983 GL CONSERVATION DIVISION I did [10 1			
Completed: Hour: 7:15A.M., Day: 7 , Month: December , Year: 93 Actual plugging report: 1st. plug at 2670' w/25 sxs. 2nd. plug at 1830' w/100 sxs. 3rd. plug at 315' w/40 sxs. 4th. plug at 40' w/10 sxs. 15 sxs. in rathole. Remarks: By: Allied Cementing. No arbuckle. Condition of casing(in hole): GOOD BAD Anhy.plug: YES NO NO NO NOTE 15 1993 Plugged through TUBING , CASING . Elevation: 2983 GL CONSERVATION DIVISION I did [V 0	Plugging Proposal Received by: Ed Sc	humacher	
Actual plugging report: 1st. plug at 2670' w/25 sxs. 2nd. plug at 1830' w/100 sxs. 3rd. plug at 315' w/40 sxs. 4th. plug at 40' w/10 sxs. 15 sxs. in rathole. RECEIVED STATE COMPORTATION COMMISS Condition of casing(in hole):GOOD BAD Anhy.plug:YES NO Bottom plug(in place):YES , CALC , NO X Dakota plug:YES NO Plugged through TUBING , CASING . Elevation: 2983 GL CONSERVATION DIVISION I did [V 01 Pig 19t [X] observe the plugging.	Plugging operations attended by agent?	All[], Part[], None[X]	
Ist. plug at 2670' w/25 sxs. 2nd. plug at 1830' w/100 sxs. 3rd. plug at 315' w/40 sxs. 4th. plug at 40' w/10 sxs. 15 sxs. in rathole. Remarks: By: Allied Cementing. No arbuckle. Condition of casing(in hole):GOODBADAnhy.plug:YESNODEC_15 1993 Bottom plug(in place):YES,CALC,NOXDakota plug:YES,NODEC_15 1993 Plugged through TUBING, CASING Elevation: 2983 GL CONSERVATION DIVISION I did[[V 1 Air rot[X] observe the plugging.	Completed: Hour: 7:15A.M., Day: 7, Mo	onth: <u>December</u> , Year: 93	
Ist. plug at 2670' w/25 sxs. 2nd. plug at 1830' w/100 sxs. 3rd. plug at 315' w/40 sxs. 4th. plug at 40' w/10 sxs. 15 sxs. in rathole. Remarks: By: Allied Cementing. No arbuckle. Condition of casing(in hole):GOOD BAD Anhy.plug:YES NO DEC 15 1993 Bottom plug(in place):YES , CALC , NO X Dakota plug:YES NO DEC 15 1993 Plugged through TUBING , CASING . Elevation: 2983 GL CONSERVATION DIVISION I did[V 1 Air rot[X] observe the plugging.	Actual plugging report:		
Remarks: By: Allied Cementing. No arbuckle. Remarks: By: Allied Cementing. No arbuckle. Condition of casing(in hole):GOOD BAD Anhy.plug:YES NO NO Bottom plug(in place):YES ,CALC ,NO \ Dakota plug:YES \ NO \ Dakota plug:YES \ Dako	1st. plug at 2670' w/25 sxs.		
Ath. plug at 40' w/10 sxs. 15 sxs. in rathole. RECEIVED Remarks:By: Allied Cementing. No arbuckle	2nd. plug at 1830' w/100 sxs.		
Remarks:	4th plug at 401 w/10 sys		
Remarks: By: Allied Cementing. No arbuckle. Condition of casing(in hole):GOOD BAD Anhy.plug:YES NO NO DEC 1 5 1993 Bottom plug(in place):YES ,CALC ,NO X Dakota plug:YES NO NO DEC 1 5 1993 Plugged through TUBING , CASING . Elevation: 2983 GL CONSERVATION DIVISION I did[V) Air rot[X] observe the plugging.	15 sys. in rathole.		
Remarks:			
Remarks:		BECEIVED	
Plugged through TUBING, CASING Elevation:	Remarks: By: Allied Cementing. No	arbuckle. STATE CORDORATION COMMISS	
Plugged through TUBING, CASING Elevation: 2983 GL CONSERVATION DIVISION I did[V 01 Pit 19t[X] observe the plugging. Cd Achumacher Conservation Division Conservation Division Conservation Conserv	Condition of casing(in hole):GOODB	Anhy.plug:YES V NO NO A F 1007	
I did[V 01 pit rot[x] observe the plugging. Ed Schumecher Conservation Division 1 did[V 01 pit rot[x] observe the plugging.	Bottom plug(in place):YES,CALC	,NOXDakota plug:YES/,NO	
DATE $\frac{12-30-93}{39611}$ observe the plugging. Ed Schumacher Marsas (agent)	Plugged through Tubing . Casing	. Elevation: 2983 GL	
DATE $12-30-93$ (agent) Form CP-2/3	I did[V) 1 Cif Tot[x] observe the p	olugging. Ed Schumacher Winds	
DATE 3 96 11	12-30-93	(agent)	
	29611	Form CP-2/3	