| To:   | API NUMBER   | 15-07                                 | 3-194                                | 50-00-00  |
|---|--|---------------------------------------|--------------------------------------|---|
| STATE CORPORATION COMMISSION  | NW-NW-SE   | Sec/Twp/Rge                           | 23-24-12                             | E   |
| Wichita State Office Bldg PLUGGING SECTION  | 2520'  | _feet from so                         | uth section                          | line 🔎  |
| 130 S. Market, Room 2078<br>Wichita, Kansas 67202   | 2640'  | _feet from ea                         | st section lin                       | ne \$ 35  |
| TECHNICIAN'S PLUGGING REPORT  | Lease/Well#  | JOHNSON #                             | <b>‡</b> 19                          |   |
| Operator License # 7791   | County   | GREENWO                               | DD                                   | a town of the control  |
| Operator: C. W. OIL PRODUCER  | Well Total Depth   | 470'                                  |                                      | feet  |
| Name & P.O. BOX 146   | Production Pipe:   | 8"                                    | Size Feet                            | 129'  |
| Address GRIDLEY,KS. 66852   | Surface Casing:  | 10"                                   | Size Feet                            | 400'  |
| AB oil well Gas Well SWD We   | II/ Input Well   |                                       | D & A                                |   |
| Other well as hereinafter indicated: WATER  | SUPPLY WELL  |                                       |                                      |   |
| Plugging Contractor: C. W. OIL PRODUCER   | **************************************                                   |                                       | Lic.#                                | 7791  |
| Address: P.O. BOX 146 GRIDLEY,KS. 66852   |  |                                       |                                      | 1   |
| Company to plug at: Hour:Day:   | 13   | Month:                                | 8                                    | 2005  |
| Plugging proposal received from:  |  |                                       |                                      | 5557-000-0-1-7551-1-1-75  |
| Company Name:   |  | _Phone:                               |                                      |   |
| Were: 50' CEMENT PLUG @ 470' 150' CEMENT  | FPLUG TO SURFA   | ACE.                                  |                                      | ***************************************   |
|   |  |                                       |                                      |   |
| Plugging Proposal P   | ossived by   | MNIIVE HEE                            | EEDN                                 | 4 - 117 - 127 |
| Plugging Proposal R   | eceived by:  | MNIKE HEF                             | FERN<br>TECHNICIAN                   |   |
| Plugging Proposal R Plugging attended by Agent: All   | eceived by:<br>Part  | MNIKE HEF                             | TECHNICIAN                           | I   |
|   | Part   |                                       | TECHNICIAN                           |   |
| Plugging attended by Agent:  Operations Completed: Hour:  Actual Plugging Report:  PUMPED 10 SXS CI   | Part<br>16<br>EMENT THRU TUE   | XXXXXXXX<br>6 Month:<br>BING @ 470' F | TECHNICIAN<br>None<br>8<br>PULLED TU | 2005<br>JBING TO  |
| Plugging attended by Agent: All Operations Completed: Hour: Day:  | Part<br>16<br>EMENT THRU TUE   | XXXXXXXX<br>6 Month:<br>BING @ 470' F | TECHNICIAN<br>None<br>8<br>PULLED TU | 2005<br>JBING TO  |
| Plugging attended by Agent:  Operations Completed: Hour:  Actual Plugging Report:  PUMPED 10 SXS CI   | Part<br>16<br>EMENT THRU TUE   | XXXXXXXX<br>6 Month:<br>BING @ 470' F | TECHNICIAN<br>None<br>8<br>PULLED TU | 2005<br>JBING TO  |
| Plugging attended by Agent: All  Operations Completed: Hour: Day:  Actual Plugging Report: PUMPED 10 SXS CI  150' CIRC. CEMENT TO SURFACE. 115 SX CEMENT  | Part<br>16<br>EMENT THRU TUE   | XXXXXXXX<br>6 Month:<br>BING @ 470' F | TECHNICIAN<br>None<br>8<br>PULLED TU | 2005<br>JBING TO  |
| Plugging attended by Agent: All  Operations Completed: Hour: Day:  Actual Plugging Report: PUMPED 10 SXS CI  150' CIRC. CEMENT TO SURFACE. 115 SX CEMENT  | Part<br>16<br>EMENT THRU TUE   | XXXXXXXX<br>6 Month:<br>BING @ 470' F | TECHNICIAN<br>None<br>8<br>PULLED TU | 2005<br>JBING TO  |
| Plugging attended by Agent: All  Operations Completed: Hour: Day:  Actual Plugging Report: PUMPED 10 SXS CI  150' CIRC. CEMENT TO SURFACE. 115 SX CEMENT  | Part<br>16<br>EMENT THRU TUE   | XXXXXXXX<br>6 Month:<br>BING @ 470' F | TECHNICIAN<br>None<br>8<br>PULLED TU | 2005<br>JBING TO  |
| Plugging attended by Agent: All  Operations Completed: Hour: Day:  Actual Plugging Report: PUMPED 10 SXS CI  150' CIRC. CEMENT TO SURFACE. 115 SX CEMENT  | Part<br>16<br>EMENT THRU TUE   | XXXXXXXX<br>6 Month:<br>BING @ 470' F | TECHNICIAN<br>None<br>8<br>PULLED TU | 2005<br>JBING TO  |
| Plugging attended by Agent: All  Operations Completed: Hour: Day:  Actual Plugging Report: PUMPED 10 SXS CI  150' CIRC. CEMENT TO SURFACE. 115 SX CEMENT  | Part10 EMENT THRU TUE , CEMENT FELL B                                    | XXXXXXXX<br>6 Month:<br>BING @ 470' F | TECHNICIAN<br>None<br>8<br>PULLED TU | 2005<br>JBING TO  |
| Plugging attended by Agent: All Operations Completed: Hour: Day: Actual Plugging Report: PUMPED 10 SXS CI 150' CIRC. CEMENT TO SURFACE. 115 SX CEMENT CEMENT.  Remarks:   | Part10 EMENT THRU TUE , CEMENT FELL B                                    | XXXXXXXX<br>6 Month:<br>BING @ 470' F | TECHNICIAN<br>None<br>8<br>PULLED TU | 2005<br>JBING TO  |
| Plugging attended by Agent: All  Operations Completed: Hour: Day:  Actual Plugging Report: PUMPED 10 SXS CI  150' CIRC. CEMENT TO SURFACE. 115 SX CEMENT  CEMENT.  Remarks: (If additional description is necessary, us | Part10 EMENT THRU TUE , CEMENT FELL B                                    | XXXXXXXX<br>6 Month:<br>BING @ 470' F | PULLED TUPED OFF V                   | 2005<br>JBING TO  |
| Plugging attended by Agent: All  Operations Completed: Hour: Day:  Actual Plugging Report: PUMPED 10 SXS CI  150' CIRC. CEMENT TO SURFACE. 115 SX CEMENT  CEMENT.  Remarks: (If additional description is necessary, us | Part Part Part   | XXXXXXXX<br>6 Month:<br>BING @ 470' F | TECHNICIAN<br>None<br>8<br>PULLED TU | 2005<br>JBING TO  |
| Plugging attended by Agent:  Operations Completed: Hour:  Actual Plugging Report:  150' CIRC. CEMENT TO SURFACE. 115 SX CEMENT CEMENT.  Remarks:  (If additional description is necessary, us observe this plugging.    | PartPart16 EMENT THRU TUE , CEMENT FELL B se BACK of this form.) Signed: | XXXXXXXX<br>6 Month:<br>BING @ 470' F | PULLED TUPED OFF V                   | 2005<br>JBING TO  |