3 022716

| To: | API NUMBER | CONTROL NO. 20040041 | | |
|---|--|---|---------------------------------------|--|
| STATE CORPORATION COMMISSION | NW SW,SW 1/4 | Sec/Twp/Rge S.34-T.26SR.16E. | | SR.16E. |
| Wichita State Office Bldg PLUGGING SECTION | 875 | feet from south section line | | |
| 130 S. Market, Room 2078 Wichita, Kansas 67202 | 4683 | feet from ea | st section lir | ne |
| TECHNICIAN'S PLUGGING REPORT | Lease/Well# | APT NO. 10-I | | |
| Operator License # | County | WOODSON | | |
| Operator: STATE OF KANSAS FEEFUND | Well Total Depth | 1000' | | feet |
| Name & FEE FUND PLUGGING | Production Pipe: | 2" | _Size Feet | 1000' |
| Address | Surface Casing: | 6" | _Size Feet | 20' |
| AB oil well X Gas Well SWD Well/ | 'input Well | | _D & A | |
| Other well as hereinafter indicated: | | | | |
| Plugging Contractor: SPLANE PULLING AND ROUSTA | ABOUT SERVICE | | _Lic.# | 6372 |
| Address: BOX 386, RR4, CHANUTE, KANSAS 66720 | | | | |
| Company to plug at: Hour: 9:30A.M. Day: | 13 | Month: | 4 | 2005 |
| Plugging proposal received from: CLAYTON P. TITEL | | | | |
| Company Name: KANSAS CORPORATION COMM | IISSION | Phone: | 620-432-23 | 300 |
| Were: THIS WELL CONSISTED OF 2" CASING TO | APPROXIMATEL | Y 1000' THA | T HAD | |
| BEEN CEMETNED IN AT T.D. ONLY. 1" PIPE HAD BEE | N "LEFT HANDE | O" FROM TH | E WELL | |
| TO 525'. PROBABLY 1" PIPE REMAINS IN THE WELL F | ROM 525' TO NE | AR T.D TH | E PLUGGIN | G |
| PROPOSAL IS TO CIRCLATE AS MUCH OF THE WELL | AS POSSIBLE F | ULL OF CEN | MENT. | |
| Plugging Proposal Red | ceived by: | CLAYTON F | P. TITEL | |
| Plugging attended by Agent: All | Part | | TECHNICIAN None | X |
| Operations Completed: Hour: 12:3OP.M. Day: | 13 | Month: | 4 | 2005 |
| Actual Plugging Report: 3/4" PIPE WAS RAN II | - 100mm | • | CEMENT | |
| WAS PUMPED INTO THE 3/4" PIPE UNTIL CEMENT CI | | | | Northean Control of the Control of t |
| SURFACE. THE 3/4" PIPE WAS REMOVED. 1" PIPE WA | | *************************************** | · · · · · · · · · · · · · · · · · · · | The second secon |
| TO 300'. CEMENT WAS PUMPED INTO THE 1" PIPE UN | | | | |
| THE SURFACE CASING AT SURFACE. THE 1" PIPE W. | | | | |
| FILLED FROM SURFACE.69 SACKS OF CEMENT WER | | | | 27 - Andrews . Physical |
| | ************************************** | | | RECEIVE |
| Remarks: (GPS SESSION PT. NO. 73) (THIS WELL W | /AS NO.10-I ON 1 | THE LEASE I | MAP.) | APR 2 8 200 |
| (If additional description is necessary, use I | BACK of this form.) | | | KCC WICHI |
| I DID NOT observe this plugging. | | | | n n n n n n n n n n n n n n n n n n |
| | Signed: | Class | D Tito | |

m