

DISTRICT CONSERVATION AGENT'S REPORT

TO:

15-163-00413-00-00

8

State Corporation Commission
Conservation Division
211 North Broadway
Wichita, Kansas

FILE NO. 127-17

LOCATION NE NW SE

SEC. 18 TWP. 8 RGE. 16W

Dry Hole Abandoned Oil Well Abandoned Gas Well _____

I have this date completed supervision of plugging of:

Well No. 1 Lease Chesney

Operator Herndon Drg Co Address 423 Mayo Bldg Tulsa, Okla

Field _____ County Rooks

Total Depth 3087 Feet.

Plugging Contractor West Supply Co

Plugging Contractor's License No. 14

Address _____
(Describe briefly the manner in which the well was plugged)

8 5/8" at 255' circulated with cement - 5 1/2" at 3087' circulated
to 0' with cement - perforated at 3049'

Filled with sand to 3030', set 4 sax cement with dump baller,

filled with mud to 300', set rock and 5 sax cement - mud to 40',

set rock and 5 sax cement to bottom cellar.

no pipe recovery.

E. J. ...

District Conservation Agent

Date 6-24-55

6-29-55

RECEIVED
STATE CORPORATION COMMISSION

JUN 29 1955

CONSERVATION DIVISION
Wichita, Kansas

PLUGGING
FILE SEC. 18 T. 8 R. 16W
BOOK PAGE 127 LINE 17