DISTRICT CONSERVATION AGENT'S REPORT

TO:

B-163-02674-00-UO

State Corporation Commission Conservation Division 800 Bitting Building Wichita, Kansas

	FILE NO. 105-22
	LOCATION SW NW NE
	SEC. 5 TWP. 8 RGE. 17
Dry Hole Abandoned Cil Well Aband	doned Gas Well
I have today completed supervision of plugging of: D-1 Stamper Well No. Lease	
Operator Murfin Drg Co Address	Vichita, Kans
FieldCounty	Rooks
Total Depth 5359 Feet.	
(Describe briefly the manner in which the well was plugged) 8 $5/8^n$ at 122^n circulated with cement - $5\frac{1}{2}$ at 3345^n with 50 sax cement behind.	
Filled with chat to 3330, set 4 sax cem	ent with dump bailer.
pulled 2500' $5\frac{1}{2}$ " - pumped in 50 sax mud,	filling hole, pumped
in cementing plug to 1851, followed by 6	O sax cement filling
hole from 185' toO' with cement.	
Cementing by Sun Cementing Co	
PLUGGING PLE SEC. T. & R. /2// MATE OF THE PROPERTY SECONDARY SECO	District Conservation Agent

CONSERVATION DIVISION Date 0-13-53
Wighita, Kansas 7-53