DISTRICT CONSERVATION AGENT'S REPORT



TO:		, pro construction / spokens	Sindhan anagailteaga is in san
State Corporation Commission Conservation Division 211 North Broadway	99-42 FILE NO.		
Wichita, Kansas	LOCATION	SV 38W	NE
	SEC. 2	TWP.7 I	RGE2"
Dry Hole X Abandoned Oil Well Abandoned Gas V	Well		
I have this date completed supervision of plugging of:			
Well No. l Lease Sniffen			
Operator Anschutz Drg Co Address 709 Unio	n Natl	Wichita	. 9
FieldCounty_Sheridan			
Total Depth 4080 Feet.			
Plugging Contractor E & L Casing Pulling			
Plugging Contractor's License No. 249			
\cdot			
Address (Describe Briefly the manner in which the well			
8 5/8" at 165' circulated with cement - $5\frac{1}{2}$ " at 39	10' with	100	
sax cement behind - Lane Wells plugs to 38491, pe	rforated	3840°.	
Sand to 3830', set 4 sax cement with dump bailer,	pulled	24001	
$\mathfrak{d}_{\mathbb{R}}^{\frac{1}{2}^{n}}$ Θ heavy mud to 350', set rock bridge and 30 s	ax cemen	t, mud	Material control for management depote
to 35', set bridge and 10 sax cement to bottom ce	llar.		Allega (and a part of the par
			Parisional Control of the Control of
			Marine and the second s
Eldon) hety		Market according population and according to
District Cons	servation <i>l</i>	Agent	
Date		SCORE CONTRACTOR OF THE PROPERTY OF THE PROPER	Marie and Marie and Appear
PLUGGING) E	D Ission	

FILE SEC 2 T 7 R 27W BOOK PAGE 99 LINE 42

" " LUCES