## KANSAS STATE CORPORATION COMMISSION

## CONSERVATION DIVISION AGENT'S REPORT

TO:

Jewel M. Ogden, Director	
500 Insurance Building	
212 North Market	
Wichita 2, Kansas	
File NoCounty:	Graham
	Sec. <u>23</u> Twp. <u>7</u> Rge. <u>23</u> (E) (W) <u>\( \nabla \) </u>
Name of Field: 701/1 Cat	Total Depth: 3760
I have this date completed supervision of p	
Lease Name: TREXLER	Well No. ≠/
Operator's Full Name: PE+ROLEUM	INC.
Complete Address: 325 N. Brode	I way, Wichita, Ks.
Plugging Contractor: Same.	
Address:	License No.
Oil Well Gas Well Input N	WellD & A
Other well as hereafter indicated:	
Was any delay in plugging operations caused	by Conservation Division Agent? YesNo
If yes how long?	Reason:
Operation Completed: Hour 6 P.M. Day	30 Month SEPT Year S8
The above well was plugged as follows:	
Mudded BACK to 600'SE.	+ CEMENTING Plugt 20 SX
CEMENT- Mudded BACK	to 215 SETCEMENTING Plag
+20 SX (EMEIX+ - Mudded	ROJERTO 40 SET CEMENTUNG
Plug + 10 SX CEMENT TO B	ASE OF CEllar, 220'07878'
SURFACE CASING	
	Signed: 7 A Conservation Division Agent
_p	Conservation Division Agent
Reviewed: Jewis Brock Field Supervisor	
Field Supervisor	and the second of the second o
Pomovles	the state of the s
Remarks:	
hund A h	1001111