DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission Conservation Division 800 Bitting Building Wichita, Kansas

BOOK PAGE 118 LI E 37



Wichita, Kansas	
national manifolds	FILE NO. 118-37
1	LOCATION SE SE NW
	SEC. 19 TWP. 8 RGE. 17
Dry Hole Abandoned Oil Well * Abandoned G	as Well
I have this date completed supervision of plugging Schindler	ng of:
Well No. Lease	Paggal 7 Vans
	Russell, Kans
FieldCounty_	Rooks
Total Depth 3408 Feet.	
Plugging Contractor Barnes & Sons	
Plugging Contractor's License No. 9	
Address	
(Describe briefly the manner in which	the well was plugged)
8 5/8" at 116' circulated with cement -	5½" at 3403' with
25 sax cement behind - Squeezed in Dako	
Filled with sand to 3390', set 4 sax ce	ment with dump bailer.
pulled 460' $5\frac{1}{2}$ " - pumped hole full mud	
cementing plug to 2201, followed by 70 s	BID 3. MERITANIST MERITANIST WAS CONTROL OF
Mudding and cementing by Halliburton Co	
	Annual Annua
\$*\hat{\sigma} \tag{\sigma} -	11
STATE CONTROLL VIEW	District Conservation Agent
PLUGGING	N Date 1-7-57
FILE SEC 19 T & DIME	

Wichita, Kansas