TO:	API number: 15-141-20,282-00-00
STATE CORPORATION COMMISSION	
CONSERVATION DIVISION - PLUGGING	SW SW NW /4 SEC. 24 , 10 S , 12 W
200 COLORADO DERBY BUILDING WICHITA, KANSAS 67202	<u>2970</u> feet from S section line 4950 feet from E section line
TICHTIA, IMMORD 0/202	1930 reet from E Section fine
Operator license# <u>3293</u>	Lease <u>Schultz "A"</u> well # <u>1</u>
Operator: Russell Oil, Inc.	County Osborne
Address: P.O. Box 272	Well total depth 3230 feet
Russell, Kansas 67665	Well total depth <u>3230</u> feet Conductor Pipe: <u>0</u> inch @ <u>0</u> feet
	Surface pipe 8 5/8 Inch @ _218 _ feet
Aband. oil well, Gas well, Inp	w/145 sx. out well, SWD, D & A <u>X</u>
Plugging contractor: Shields Drilling License# 5184	
Address: Russell, Kansas 67665	
Company to plug at: Hour: P.M. Day:	_16 Month: December Year: 93
Plugging proposal received from: Burt Berry	
Company: Shields Drilling	Phone:
Were: Order 180 sxs. 60/40 pozmix - 6% gel - 1/4# flocele per. sx.	
Plugging Proposal Received by: <u>Dennis</u>	. Hamal
Plugging operations attended by agent? All[], Part[], None[X]	
Completed: Hour: 2:00P.M., Day: 16, Mo	onth: <u>December</u> , Year: <u>93</u>
Actual plugging report:	
Spot plugs through drill pipe with hea	vy mud between all plugs.
1st. plug @ top ** W/25 sxs.	
2114: PIUG & 700 W/25 SAS.	
3rd. plug @ 515' w/100 sxs. 4th. plug @ 40' w/10 sxs.	
Rathole with 15 sxs.	
MONGODOLO With the TO corre	12-21-93
Domonica. Coment has \$111.1	Figure 2 and
Remarks: Cement by: Allied Condition of casing (in hole): COOD	AD Anhy plug. VES Y NO STATE PROPERTY STATES
Condition of casing(in hole):GOOD BAD Anhy.plug:YES X NO GIATE OF STATE OF	
Plugged through TUBING, CASING	Elevation: 1666 GL
I dld V O did not [x] observe the p	Λ
DATE 12-30-93	. •
39609	(agent)
INV. NO. 12-16	Form CP-2/3