TO: STATE CORPORATION COMMISSION CONSERVATION DIVISION - PLUGGING 130 SOUTH MARKET, SUITE 2078 WICHITA, KANSAS 67202	API Number: 15-141-20,177-00-00 NE NW NW /4 SEC. 15 , 10 S, 14 W 330 feet from N section line 3920 feet from W section line
Operator license# 9141	Lease: <u>Meyer</u> Well # 1
Operator: Double Ace Oil	County: Osborne
Address: 815 Main Victoria, Kansas 67671	Well total depth 3700 feet Conductor Pipe: 0 inch @ 0 feet Surface pipe 8 5/8 Inch @ 208 feet w/145 sxs.
Aband. oil well_x, Gas well, Input well_	, SWD, D & A
Plugging contractor: <u>Mike's Testing Service</u>	License#
Address: Chase, Kansas 67524	
Company to plug at: Hour: 11:00 A.M. Day: 23 Mor	nth: January Year 1996
Plugging proposal received from: Mike Kelso	
Company: Mike's Testing Service Phone:	
Were: 5 1/2" casing set at 3510' w/150 sxs cement. Perfs at 3255' - 3395'. Ordered 265 sxs. 60/40 pozmix - 10% gel with 1/4# F.C. plus 600# hulls. Plug bottom with sand to 3200', plus 5 sxs cement on sand.	
Plugging Proposal Received by: Herb Deines Plugging operations attended by agent? All[X], Part[], None[]	
Completed: Hour: 8:00 P.M., Day: 23, Month: January, Year: 1996	
Actual plugging report: Shot casing at 2200' and recovered same. Plugged as follows: pulled casing to 1750' - pumped 115 sxs with 300# hulls - pulled casing to 1225' - pumped 35 sxs with 100# hulls - pulled casing to 100' - pumped 35 sxs cement with 200# hulls - pulled casing to 250' - pumped 50 sxs cement to circulate at surface with cement. Pulled balance	
of casing and topped off with 10 sxs cement.	ate at surface with cement. Pulled balance
Remarks:	-96 30 CEN
Condition of casing(in hole): GOOD BAD_ Bottom plug(in place): YES, CALC, NO	Anhy.plug: YES X NO OTT
Plugged through TUBING, CASING	Dakota plug: YES X NO GL
I did[X / did hot]] observe the plugging.	July Valor
JAN 3 0 1996	(agent) Form CP-2/3
DATE 11 4763	
MV. NO. 4 TT /C	