DISTRICT CONSERVATION AGENT'S REPORT



TO;

State Corporation Commission Conservation Division 800 Bitting Building Wichita, Kansas

witching od , manbab	
	FILE NO.
	LOCATION NW NW SW
1	SEC. 4 TWP. 9 RGE. 18 W
Dry Hole X Abandoned Oil Well	Abandoned Gas Well
I have today completed supervision of	Plugging of:
Well No. 1 Lease F	lavlas
Operator Brunson Drg Co Address	
FieldCounty	Rooks
Total Depth 3078 Feet.	
(Describe briefly the manner in	which the well was plugged)
8 5/8" at 195' circulated with	cement.
Heavy rotary mud to 195', wood	plug and lo sax cement -
Heavy mud to 35', wood plug, r	ock and 10 sax cement to
bottom cellar.	
	is a margin and the first of the graph of margin states or a product of the debt of the debt of the control for an article of the debt of
and the second s	managan aga ngang naga galas gapan andan an agan da sa nakanada da nakanada an an akanada an an akanada an an a
and a second and a	
man and an analysis of the second section of the sec	
	Les Land
FR	District Conservation Agent
D	ate 1-31-49