15-163-02591-20-00

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission Conservation Division 211 North Broadway	FILE NO.
Vichita, Kansas	LOCATION SE NW NW
	SEC. 30 TWP. 9 RGE. 18
Dry Hole Abandoned Oil Well Aba	
Well No. 1 Lease Hilgers	
Operator Walters Drg Co	Address Wichlia Kans
Total Depth 3715 Feet.	Annual Control of the
Plugging Contractor same	
Plugging Contractor's License No.	
Address (Describe briefly the mann	er in which the well was plugged)
8 5/8" at 1/1' circulated with c	emen.t.
Circulated hole with heavy mud,	set cementing plug at lost,
1/2 sack hulls and 15 sax cement	, mud to 401, set cementing plug,
1/2 sack hulls and 10 sax cement	to bottom collar.
We see that the second	1900 produkturilizar-i (filosophian-dagi) i plantishupun dalah dagi palas-dasappilan-dagi phytophiakan-asar yarkushukappin-unit-basi gay, takabukutu, biga manakan sebagi p
	Ellen Lein
	District Conservation Agent
	Date
PLUSGING 18w	

100K PAGE 128 UNE 18

THE TWINGS ON WEIGH Violita, Kanoas