DISTRICT CONSERVATION AGENT'S REPORT

K,

TO:

State Corporation Commission Conservation Division 800 Bitting Building Wichita, Kansas

800 Bitting Building Wichita, Kansas	
wichitody handab	FILE NO. 105-23
	LOCATION NE NE NW
	SEC. 11 TWP. 9 RGE. 20
Dry Hole X Abandoned Cil Well	Abandoned Gas Well
I have today completed supervision of plugging	of:
Well No. 1 Lease Balo	lwin
Operator Musgrove Pet Co Addre	ss Wichita, Kans
FieldCount;	y Roo ks
Total Depth 3667 Feet.	
(Describe briefly the manner in which the well was plugged)	
8 5/8" at 192' circulated with cement - 51 at 3621'	
with loo sax cement behind.	
Baker plugs at 3472' - perforated at 3591' - filled with chat	
to 3370', set a sax cement with dump bailer - pulled 2850'	
$0\frac{1}{2}$, filled with mud to 190', set rock and lo sax cement -	
mud to bot, set rock and 10 sax cement to bottom cellar.	
Street and the street	
	Jan Jest
11+ 9 20W	District Conservation Agent
	n-18-55