

DISTRICT CONSERVATION AGENT'S REPORT

15-163-03964-00-00

TO:

State Corporation Commission
Conservation Division
800 Bitting Building
Wichita, Kansas

FILE NO. _____

LOCATION NE-NE-NE

SEC. 2 TWP. 8 RGE. ~~18W~~ 19W

Dry Hole X Abandoned Oil Well _____ Abandoned Gas Well _____

I have today completed supervision of plugging of:

Well No. 1 Lease Ellis

Operator Wentworth Standard Oil Co Address 1022 Union Natl. Bank Bldg - Wichita

Field Milledred Drilling Co. County Rooks

Total Depth 3370 Feet.

(Describe briefly the manner in which the well was plugged)

Surface Pipe 10 3/4 - 182 ft. Circulated with Cement.

Surface Pipe 8 3/4 - 690 ft. Cemented with 1100 sacks Cement.

This well started flowing water from The Dakota Sand at 400 ft. - that is the reason the 6 3/8 casing was put in

& the two strings of Surface Pipe - 10 3/4 & 8 3/4 cemented together - shutting off the water - Hole full of heavy mud

from bottom to 245 ft. Set Plug & 85 sacks cement at 295 ft. - filling hole up to the surface with cement.

Cement Pumped in by Halliburton Oil Well Cementing Co

C. N. Strong
District Conservation Agent

Date 11-25-47
NOV 28 1947

PLUGGING
FILE SEC 2 T 8 R 19W
BOOK PAGE 1 LINE 77

11-28-47