

15-163-21466-00-01

KANSAS  
STATE CORPORATION COMMISSION  
CONSERVATION DIVISION AGENT'S REPORT

RECEIVED  
STATE CORPORATION COMMISSION  
6/29/59  
JUN 29 1959  
CONSERVATION DIVISION  
Wichita, Kansas

*R*

TO:  
Jewel M. Ogden, Director  
500 Insurance Building  
212 North Market  
Wichita 2, Kansas

File No. 44-29 County: Rooks  
Location: SE SE SW Sec. 33 Twp. 8 Rge. 19 (E) (W)

Name of Field: \_\_\_\_\_ Total Depth: 3889

I have this date completed supervision of plugging of:  
Lease Name: Webster SWD Well No. SWD #1

Operator's Full Name: Skelly Oil Co

Complete Address: Box 1650 Tulsa, Okla

Plugging Contractor: Halliburton Cementing Co

Address: Hays, Kans License No. \_\_\_\_\_

Oil Well \_\_\_\_\_ Gas Well \_\_\_\_\_ Input Well \_\_\_\_\_ SWD Well X D & A \_\_\_\_\_

Other well as hereafter indicated: \_\_\_\_\_  
Was any delay in plugging operations caused by Conservation Division Agent? Yes \_\_\_\_\_ No XX  
If yes how long? \_\_\_\_\_ Reason: \_\_\_\_\_

Operation Completed: Hour 12 Noon Day 23 Month 6 Year 59

The above well was plugged as follows:  
8 5/8" at 1440' circulated with 600 sax cement - 5 1/2" 3743' with 200  
sax cement - found 5 1/2" completely disintegrated - drilled out and fished  
junk to a depth of 705' with cable tools - lost hole at 705'.  
Pumped hole full cement, open end, 130 sax cement, filled to bottom cellar.  
Cementing by Halliburton Co.

Signed: *Jewel M. Ogden*  
Conservation Division Agent

Reviewed: *J. Brock*  
Field Supervisor

Remarks: \_\_\_\_\_

PLUGGING  
FILE SEC 33 T. 8 R. 19  
BOOK PAGE 44 LINE 29