4-25

212

To: STATE CORPORATION COMMISSION			API NUMBER 15-163-21,908-00-00	
CONSERVAT	CONSERVATION DIVISION - PLUGGING SECTION			
200 COLORADO DERBY BUILDING WICHITA, KANSAS 67202 TECHNICIAN'S PLUGGING REPORT		.DING		
		PERART	1650 feet from S section 1	
			feet from E section 11	
•		17	Complete and a second part of the complete and the comple	
Namel		rvices Corp.	County Rooks 110.	
Address	Band IV Tower	r Box 3501	Well Total Depth 3390 fe	
	Topeka, KS 66	6601-3501	Conductor Pipe: Sizefeet	
			Surface Casing: Size 8 5/8 feet 245	
Abandoned	Oll Well XXXXX	XX Gas Well	Input WellD&A	
Other wel	l as hereinafte	er indicated		
			License Number 3517	
Address			License Number 3317	
			Q.F.	
oompany re	o ping ais Hour	r:3100m pay:	25 Month: April Year: 19 90	
Plugging p	proposal receiv	ved from Dick Bug	dig	
(company r	name) <u>Columbi</u> ;	ian Services Corp	• (phone 913-234-0581	
	•	t ·	. 65/35 pos 8%gel.	
	ıg through tubiy	7: 4		
		· · · · · · · · · · · · · · · · · · ·	ted to washover and retrieve. Got to 1075' whic	
			oped hole problems in Sand section with sand	
	<del>ling in wellbor</del> e		lock indicated washover pipe cutting into csg.	
ind headed	out of hole.	Plugging Pro	oposal Received by <u>Herb Deines</u>	
			(TECHNICIAN)	
		and od take		
Plugging O	Operations atter		All_XXXXXXX PartNone	
Plugging O Operations	Operations atters  Completed: Ho	lour:6:00PM Day:	: 25 Month: April Year:19 <sup>90</sup>	
Plugging O Operations ACTUAL PLU	Operations atters Completed: House	lour: <u>6:00PM</u> Day:	. 25 Month: April Year: 19 90 and pumped 100sxs. common. Cement circ to surface	
Plugging O Operations ACTUAL PLU	Operations atters Completed: House	lour: <u>6:00PM</u> Day:	. 25 Month: April Year: 19 90 and pumped 100sxs. common. Cement circ to surface	
Plugging O Operations ACTUAL PLU Well cola	Operations atter s Completed: Ho UGGING REPORT <u>Ra</u> psed in sand se	lan the to 1073 a ection and the p	25 Month: April Year: 19 90 and pumped 100sxs, common, Cement circ to surface oulled after pressured to 1000#. Tied onto csg.	
Plugging O Operations ACTUAL PLU Well colar and press	Operations atters Completed: House Completed: House Completed: House Completed: House Complete Complet	dan the to 1073 a section and the pressure of 1000 #	Month: April Year: 19 90  and pumped 100sxs. common. Cement circ to surfactualled after pressured to 1000#. Tied onto csg.  and STP of 1000#. Tied onto appulus and pmp 10	
Plugging O Operations ACTUAL PLU Well colar and pressu sxs. 65/3	Operations atters Completed: House Completed: House Completed: House Completed: House Complete Complet	dan the to 1073 a section and the pressure of 1000 #	25 Month: April Year: 19 90 and pumped 100sxs, common, Cement circ to surface oulled after pressured to 1000#. Tied onto csg.	
Plugging O Operations ACTUAL PLU Well colar and pressu sxs. 65/3	Operations atters Completed: House Completed: House Completed: House Completed: House Complete Complet	dan the to 1073 a section and the pressure of 1000 #	Month: April Year: 19 90  and pumped 100sxs. common. Cement circ to surfactualled after pressured to 1000#. Tied onto csg.  and STP of 1000#. Tied onto appulus and pmp 10	
Plugging 0 Operations ACTUAL PLU Well colar and pressuand pressuan	Operations atters Completed: House Completed: House Completed: House Completed: House Complete Complet	dan the to 1073 a section and the pressure of 1000 #	Month: April Year: 19 90 and pumped 100sxs. common. Cement circ to surface pulled after pressured to 1000#. Tied onto csg. and STP of 1000#. Tied onto annulus and pmp 10 STP 200#. Cement didn't settle overnight and response to the settle overnight and response to the settle overnight.	
Plugging O Operations ACTUAL PLU Well colar and pressu sxs. 65/3	Operations atters Completed: House Completed: House Completed: House Completed: House Complete Complet	dan the to 1073 a section and the pressure of 1000 #	Month: April Year: 19 90 and pumped 100sxs. common. Cement circ to surface pulled after pressured to 1000#. Tied onto csg. and STP of 1000#. Tied onto annulus and pmp 10 STP 200#. Cement didn't settle overnight and response to the settle overnight and response to the settle overnight.	
Plugging 0 Operations ACTUAL PLU Well colar and press sxs. 65/3 at surface	Departions atters Completed: House Compl	tan the to 1073 a section and the pessure of 1000 #  ax pressure 400#  ax pressure 400#  ax pressure 400#	Month: April Year: 19 90  and pumped 100sxs. common. Cement circ to surfactualled after pressured to 1000#. Tied onto csg.  and STP of 1000#. Tied onto appulus and pmp 10	
Plugging O Operations ACTUAL PLU Well colar and pressuand pressuan	Departions atters Completed: House Compl	dan the to 1073 a section and the pressure of 1000 #	Month: April Year: 19 90 and pumped 100sxs. common. Cement circ to surface pulled after pressured to 1000#. Tied onto csg. and STP of 1000#. Tied onto annulus and pmp 10 STP 200#. Cement didn't settle overnight and response to the settle overnight and response to the settle overnight.	

Herb Deines