DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission Conservation Division 800 Bitting Building Wichita, Kansas



	FILE NO. 34-6
	LOCATION CN/2-SE-SW
	SEC.22TWP.9 RGE.2/
Dry Hole Abandoned Oil Well Abandoned Gas Well	Mikelinujasa dikutanting dan dikutanting (ilik dapi dari nasa
I have this date completed supervision of plugging of:	ilandari erak ora equirala kandari uyaka-disarpen disarilgar tani Eydhiga bushandiga a sasha esililiyi disibi dibibi esil
Well No. 3 Lease Sutar	
Operator Derly Oil Co. Address Box	1030 Wichita Kans
Field County 9	
Total Depth 38/5 Feet.	
Plugging Contractor But Self	
Plugging Contractor's License No. 48	
Address Hutchinson Hans	-Marie Bay Mary - Marie Anna Anna Baratha (Marie Bay Marie Bay Marie Bay Marie Bay Mary Marie Marie Bay Ma
(Describe briefly the manner in which the	well was plugged)
Surface pipe 8 % "@ 318 Cw.C.	
uf 100 sy Cam. Sanded hale to	3800/1
4 st Cem. Shat off and milled	54" Paris
Mud to 318' Set rock lining.	Cas D St.
15 Ax Cem mud to 35' rock	Livida Co
10 st lem to chase of Cella	gran and and and and and and and and and a
The state of the s	
8/19/54	Antonial Papalitania diperiori di sensi periori antoni antoni a depermenta sensi antoni de de diversi de descri
	Jarren D. Horner
Distr	rict Conservation Agent