KANSAS STATE CORPORATION COMMISSION



CONSERVATION DIVISION AGENT'S REPORT

TO: Jewel M. Ogden, Director 500 Insurance Building 212 North Market Wichita 2, Kansas

File No. 113-8 County: Rooks	adour error
Location: SW NW NE Sec. 32 Twp. 9 Rge. 18 (E) (W)	e nsen
Name of Field: Total Depth: 3756	Wales (male)
I have this date completed supervision of plugging of:	
Lease Name: Stucky Well No. A-1	NE CONTRACTO
Operator's Full Name: Grant Oil Co	mexicus
Complete Address: 518 W K H Bldg Wichita, Kans	incoming.
Plugging Contractor: H. D. Arnett Casing Pulling	racia <u>r</u>
Address: Hoisington, Kans License No. 265	Newcork
Oil Well Gas Well Input Well SWD Well D & A x	
Other well as hereafter indicated: Old well wash down	
Was any delay in plugging operations caused by Conservation Division Agent? Yes No	
If yes how long? Reason:	
	en jaren
	HUTCH
Operation Completed: Hour 6PM Day 11 Month 7 Year 58	an party
The above well was plugged as follows:	
8 5/8" at 160' circulated with cement - 52" 3734' with 100 sax cement	
behind - P. B. to 3510' perforated 3356'.	MESTAL
Filled with chat to 3330, set 4 sax cement with dump bailer, pulled	Herman
1680' 5분" to 550', circulated hole with heavy mud at 550' through 5분".	MENTHER
40 sax gel) displaced 20 sax cement through 52" at 500, heavy mud to	#Zinas
150', displaced 20 sax cement through 52" at 150', heavy mud to 40',	ACTORIS.
set bridge and 10 sax cement to bottom cellar.	is not the
Mudding and cementing by Sun Cementing Co.	diren
Signed: Lee Teeley	
Conservation Division Agent	than
Reviewed: Janua Brock Field Supervisor	
Trera puberareas	

Remarks:

PLUGGING

FILE SEC 32T 9 RIBW

BOOK PAGE 1/3 LINE 8