KANSAS STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

TO:
j. P. Roberts
Assistant Director
500 Insurance Building
212 North Market
Wichita 2, Kansas

| wichild 29 Kansas | |
|---|--|
| File No. County: Rooks | s sýr vych a optiochem – etropia com destruiche entitier (et a statis) |
| Location: SE SE NW Sec. 4 Twp. Rge. 9 (E) 19 | (W) |
| Name of Field:Total Depth: 3471 | and primary list of the Company of t |
| I have this date completed supervision of plugging of: | |
| Lease Name: Rosticil Well No. 5 | Nga monak ramazin nanizin kalang kang mang mang mang mang mang mang mang m |
| Operator's Full Name: Morganstern & Specter | |
| Complete Address: Box 661 Russell, Kansas | apple contribution of the columnia and colum |
| Plugging Contractor Lynch Pipe Pulling | garla – ny vaky povojihojno vila tak komo vramo časta v povičin čiti rakvikoja. |
| Address: Great Bend, Kans License No. 457 | |
| OII Well x Gas Well Input Well SWD Well D&A | |
| Other well as hereafter indicated: | |
| Was any delay in plugging operations caused by Conservation Division | |
| YesNo_x | |
| if yes how long? Reason: | |
| • | |
| | |
| Operation Completed: Hour 4:30PM Day 28 Month 6 Year | 61 |
| The above well was plugged as follows: | |
| 8 5/8 1453 circulated with cement - $5\frac{1}{2}$ 3446 with 200 sax cement | t. |
| P.B. with sand to sit! 3100', set 4 sax cement with dump bailer, p | oulled |
| 2600', $5\frac{1}{8}$ " to 500', circulated hole with heavy mud through $5\frac{1}{8}$ " - di | Lsplaced |
| 20 sax cement through $5\frac{1}{2}$ " at 500', heavy mud to 180', displaced 20 | sax comer |
| through $5\frac{1}{8}$ " at 180', heavy mud to 35', set bridge and filled to be | ttom |
| cellar with cement. | |
| Mudding and cementing by Lynch Co pump truck. | tellpanapaga, rakkati sannaktellarikati kristor-kingapaniman sta sad |
| Signed: Ledon Testes Conservation Division | on Agent |
| Reviewed: March March Field Supervisor | |

Remarks:

INVOICED

DATE 7/30/61 INV. NO. 3413-W