
## DISTRICT CONSERVATION AGENT'S REPOR

hulls and 10 sax cement to bottom cellar.

| DISTRICT CONSERVATION AGENT'S REPORT   |
|--|
| TO:  |
| State Corporation Commission Conservation Division 800 Ditting Building Wichita, Kansas                  |
| FILE NO.   |
| LOCATION NW NW SE  |
| SEC. 24TWP. 9 RGE. 22 W  |
| Dry Hole X Abandoned Cil Well Abandoned Gas Well   |
| I have today completed supervision of plugging of:   |
| Well No. 1 Lease Kern  |
| Operator D. G. Hansen Address Logan, Kans  |
| FieldCounty_G**aham  |
| Total Depth 3991 Feet.   |
| (Describe briefly the manner in which the well was plugged) $8.5/8$ " at $164$ ! circulated with cement. |
| Filled with heavy mud to 155', set cementing plug, 1/2 sack hulls  |
| and 15 sax cement, mud to 40', set cementing plug, 1/2 sak   |





District Conservation Date 7-8-53