## DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission Conservation Division 211 North Broadway Wichita. Kansas

and the second s

211 North Broadway	FILE NO.
Wichita, Kansas	LOCATION SE SE NW
	SEC. 27 TWP. 9 RGE. 22 W
Dry Hole X Abandoned Cil Well Abandoned Gas We	
I have this date completed supervision of plugging of:	
Well No. 1 Lease Moore	
Operator Sunray 011 Collin Address Great Ber	nd, Kans
Field County Graham	
Total Depth 4020 Feet.	
Plugging Contractor Garvey Drg Co	
Plugging Contractor's License No.	
Address	
(Describe Briefly the manner in which the well	was plugged)
8 5/8" at 238' circulated with cement.	
Circulated hole with heavy mud, set cementing pl	lug at 228',
1/2 sack hulls and 20 sax cement, mud to 40', se	et cementing
plug, 1/2 sack hulls and 10 sax cement to bottom	cellar.
	and a second of the second of the second
	Tigermitigentia artisin ditusu anta urbal gehilikusta veenseefuleefusiontiibihtissuutnoo võlesa Tigeruta sertelahallipeassaa kõlest
	PARTS on The Company of the Parts of the Company of
Ledon	Lety .
	ervation Agent
Date 4-28-56	

PLUGGING
PLUGGING
PLUGGING
PAGE 57 UNE 33

4/30/56 6
ATION DIVISION Chite, Kenses