

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
211 North Broadway
Wichita, Kansas

FILE NO. ✓

LOCATION SW-SE-SW

SEC. 1 TWP. 26 RGE. 2E

Dry Hole ✓ Abandoned Oil Well _____ Abandoned Gas Well _____

I have this date completed supervision of plugging of:

Well No. 1 Lease De Moss

Operator Red Dalg Co Address El Dorado Kans

Field _____ County Sedgwick

Total Depth 3246 Feet.

Plugging Contractor Company Tools

Plugging Contractor's License No. _____

Address _____

(Describe Briefly the manner in which the well was plugged)

Grinded pits and circulated, hole made solid at 110', 15 5/8 cement thru 3 joints drill pipe, mud to 25', bridge, 5 5/8 cement at top.

Paul Durbek
District Conservation Agent

Date 2-20-57

RECEIVED
STATE CORPORATION COMMISSION

FEB 21 1957
CONSERVATION DIVISION
Wichita, Kansas

PLUGGING
FILE SEC. 1 T. 26 R. 2E
BOOK PAGE 142 LINE 4