

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
211 North Broadway
Wichita, Kansas

FILE NO. _____

LOCATION SE-SE-7W

SEC. 1 TWP 26 RGE. 2E

Dry Hole Abandoned Oil Well _____ Abandoned Gas Well _____

I have this date completed supervision of plugging of:

Well No. 2 Lease De Moss

Operator Red Dalg Co. Address El Dorado Kans

Field ✓ County Sedgwick

Total Depth 2845 Feet.

Plugging Contractor Wheat Supply Co, Inc.

Plugging Contractor's License No. 14

Address Chase Kans

(Describe Briefly the manner in which the well was plugged)

Reported as previously P.B. to 2808'
Sand to 2790', 6 5/8 cement at 2790', hole
mudded, hole made solid at 140', 15 5/8
cement at 140', mud to 25', bridge, 5 5/8
cement at top.

[Signature]
District Conservation Agent

Date 11-7-1957

NOV 11 1957
DIVISION
11-8-57

PLUGGING
FILE SEC 1 T 26 R 2E
BOOK PAGE 59 LINE 31