


DISTRICT CONSERVATION AGENT'S REPORT



TO:

State Corporation Commission
Conservation Division
800 Bitting Building
Wichita, Kansas

FILE NO. _____

LOCATION NE SW SESEC. 19 TWP. 27 RGE. 2E

Dry Hole _____ Abandoned Oil Well ☒ Abandoned Gas Well _____

I have today completed supervision of plugging of:

Well No. 1 Lease TrusteeOperator Aylward Prod Address WichitaField Cartborough County Butler

Total Depth _____ Feet.

(Describe briefly the manner in which the well was plugged)

7" pipe collapsed and caused no reach
bottom. Good mud to 2500'

Mud to 150'

Wood plug & rock bridge to 140'

15 cu cement 140' to 125'

Mud to base of casing

10 cu cement in bottom of casing

D. J. P. [Signature]
District Conservation Agent

Date 12-2-44

19 ²⁷ ₃₈ ^{2E} ₃₅