KANSAS STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

| 1 | O | • | | | | | | | | | | | |
|----|-----|----|------|-----|----|----|----|----|---|----|----|----|---|
| | le | we | 1 | Μ. | 0 | gd | en | 9 | D | ir | ec | to | Ľ |
| C | 0 | 0 | In | su | ra | nc | e | Bu | 1 | 1d | ĺn | g | |
| 4 | 21 | 2 | No | rt | h | Ма | rk | et | | | | | |
| Ÿ. | 7.8 | ah | å 4- | . ~ | 2 | v | | 00 | o | | | | |

15-193-00024-00-00

| Wichita 2, Kansas |
|--|
| File No. County: Thomas |
| Location: NESWSW Sec. 19 Twp. 9 Rge. 32 (E) (W) L |
| Name of Field: Total Depth: 4675 |
| I have this date completed supervision of plugging of: |
| Lease Name: K5/IAR Well No. A +1 |
| Operator's Full Name: QuAlity Supply Co. FNC, |
| Complete Address: 202 Pet. Bldg, Wichita, XS |
| Plugging Contractor: R-D CACING P. MINE CO. |
| Address: 1720 N. Wing hint for St. Hutchinso Mense No. |
| Oil Well Gas Well Input Well SWD Well D & A |
| Other well as hereafter indicated: |
| Was any delay in plugging operations caused by Conservation Division Ayent? Yes No C |
| If yes how long? Reason: |
| |
| |
| Operation Completed: Hour ZAM. Day 14 Month JAW Year 61 The above well was plugged as follows: |
| Sonded BACK to 4650' 35x CEM-MUN |
| to 470' 5' ROCK Bridge 25 SX GEM-Mud to |
| 40' S'R.B. 10 SX CEM to BASE OF CELLOR |
| to 470' 5' ROCK Bridge 25 SX CEM-Mud to 40' 5' R.B. 10 SX CEM to BASE OF CE//Jr, 480' of 103/4 SURFACE Pipe. |
| |
| |
| |
| ⁸ |
| Signed: Ab Follow |
| Conservation Division Agent |
| Reviewed: J- Murio Brock |
| Field Supervisor |
| Remarks: |

01-20-1961