



WELL LOG - Matson #2

OPERATOR: Morrison Drilling Company, Inc., et al  
 P. O. Drawer 712  
 El Dorado, Kansas

LOCATION: E/2 NE/4  
 Section 7-26S-2E  
 Sedgwick County,  
 Kansas

CONTRACTOR: Morrison Drilling Company, Inc.  
 P. O. Drawer 712  
 El Dorado, Kansas

PRODUCTION: D & A

Farm: Matson Well No. 2 Fairview Pool

Date Commenced: August 7, 1951  
 Date Completed: August 17, 1951

Total Depth: 3005' - Rotary  
 3013½' - Cable Tools

<u>From</u>	<u>To</u>	<u>Formation</u>	<u>Tops</u>	<u>Base</u>
50	96	Cement	K. C. 2541	2708
96	175	Shale & Lime brks.	Burgess 3001½	
175	300	Broken Lime		
300	530	Lime		
530	560	Shale & Shells		
560	590	Red Rock & Shale		
590	740	Lime & Shale		
740	800	Lime		
800	1300	Shale & Shells		
1300	1330	Lime		
1330	1400	Shale & Shells		
1400	1600	Lime & Shale		
1600	1710	Shale & Shells		
1710	1745	Broken Lime		
1745	1800	Shale		
1800	2030	Lime		
2030	2165	Lime & Shale		
2165	2500	Lime		
2500	2594	Broken Lime		
2594	2600	Lime		
2600	2709	Lime & Shale		
2709	2771	Lime - broken		
2771	2868	Shale & Lime brks.		
2868	3005	Lime & Shale		
3005	3013½	Sand		
3013½		Total Depth.		

I hereby certify that the foregoing is a true and correct copy of the Well Log for the Matson #2 well drilled for Morrison Drilling Company, Inc., et al and completed August 17, 1951.


MORRISON DRILLING COMPANY, INC.



C. W. Wilson - Secretary-Treasurer

STATE OF KANSAS )  
 ) ss.  
 COUNTY OF BUTLER )

SUBSCRIBED AND SWORN TO, Before the Undersigned, a Notary Public, in and for the County and State aforesaid this 22nd day of August, 1951.



My Commission Expires January 10, 1955.

  
 Notary Public

