KCC OIL/GAS REGULATORY OFFICES

Date: <u>04/07/08</u>	District: <u>01</u>	Case #:
	New Situation	Lease Inspection
	Response to Request	Complaint
	Follow-Up	Field Report
Operator License No: 3842	API Well Number: <u>15-135-24,754-</u>	· , በበበበ
Op Name: Larson Engineering, Incdba Larson Operating company	Spot: SE-NE-SW-SE Sec 30	
Address 1: 562 W State RD 4	1	Feet from N/\sqrt{S} Line of Section
Address 2:		Feet from \(\subseteq \mathbb{E} / \subseteq \mathbb{W} \) Line of Section
City: Olmitz		0.23362 Date: 4/7/08
State: Kansas Zip Code: 67564 -8561	Lease Name: Vogel	
Operator Phone #: (620) 653-7368	County: Ness	
Reason for Investigation:		
Witness Alt.II		
Problem:		
None cement circulated to surface		
		•
Persons Contacted:		
Tersons Contacted.		
	/	
Findings:		
8-5/8" @ 260' W/160sxs cement		
TD @ 4610'		
5-1/2" @ 4610' W/ 215sxs cement	1.004	·
Port Collar @ 1925' W/ 200sxs-smd-1/4# flo	seal-2%cc-15sxs went to pit.	RECEIVED KANSAS CORPORATION COMMISSION
		APR 1 1 2008
		CONSERVATION DIVISION WICHITA, KS
Action/Recommendations: Follow	w Up Required Yes No	Date:
Alt.II requirements have been met		
DECEIVED		
[] APR 1 0 2008()		
Verification Sources: Dadae City		Photos Taken:
	TA Program	
	Courthouse By: Michael Maier	
Other:		
Retain 1 Conv District Office		

Retain 1 Copy District Office Send 1 Copy to Conservation Division

02/22/2008