

# KCC OIL/GAS REGULATORY OFFICES

Date: 03/24/08

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 8996

API Well Number: 15-135-24,753-0000

Op Name: Mid-Continent Resources, Inc

Spot: SE-NW-NW-SW Sec 24 Twp 19 S Rng 22  E /  W

Address 1: P.O. Box 399

2080 Feet from  N /  S Line of Section

Address 2: \_\_\_\_\_

615 Feet from  E /  W Line of Section

City: Garden City

GPS: Lat: 38.38400 Long: 99.71880 Date: 3/24/08

State: Kc Zip Code: 67846 -0399

Lease Name: Gillig Well #: 4-24

Operator Phone #: \_\_\_\_\_

County: Ness

**Reason for Investigation:**

Witness Alt.II

**Problem:**

None cement circulated to surface

**Persons Contacted:**

\_\_\_\_\_

**Findings:**

8-5/8" @ 227' W/150sxs cement  
TD @ 4402'  
5-1/2" @ 4401' W/150sxs cement  
Port collar @ 1497' cement with 135sxs-smd-1/4# flo seal-2%cc--10sxs went to pit.

RECEIVED  
KANSAS CORPORATION COMMISSION  
APR 03 2008  
CONSERVATION DIVISION  
WICHITA, KS

**Action/Recommendations:**

Follow Up Required  Yes  No

Date: \_\_\_\_\_

Alt.II requirements have been met.

RECEIVED  
MAR 31 2008  
KCC Dodge City

**Verification Sources:**

- RBDMS
- T-I Database
- Other: \_\_\_\_\_
- KGS
- District Files

- TA Program
- Courthouse

Photos Taken: \_\_\_\_\_

By: Michael Maier

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

Form: 02/22/2008

Date: 03/24/08

District: 01

License #: 8996

Op Name: 8996

Spot: SE-NW-NW-SW Sec 24 Twp 19 S Rng 22  E  W

County: Ness

Lease Name: Gillig

Well #: 4-24

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines   
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No Ness

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-24.753-0000	2080FSL 615 FWL	SE-NW-NW-SW	38.38400-99.71188	4-24	New well, Alt. II completed