DISTRICT CONSERVATION AGENT'S REPORT



TO:

State Corporation Commission	
Conservation Division	FILE NO. 61-2
211 North Broadway Wichita, Kansas	LOCATION SW SW SE
reworked dry hole	SEC. 24 TWP. 8 RGE. 25
Dry Hole X Abandoned Oil	WellAbandoned Gas Well
I have this date completed supervisi	
Well No. 2 Lease Eng	
Operator Jones Shelburne Farme	er Address Russell, Kans
Field	
	Feet.
Plugging Contractor West Su	apply Co & Halliburton Co
Plugging Contractor's License No	
Address	
	e manner in which the well was plugged)
8 5/8" at 203' circulated w	with cement - $5\frac{1}{2}$ " at 3930' with 125 sax
cement behind - Lane Wells	plugs to 3750', perforated 3734'
Filled with sand ton3690',	set 5 sax cement with dump bailer, pulled
1200' $5\frac{1}{2}$ " to 700', circulat	ted hole with heavy mud (Gel) through
5½" - displaced 20 sax ceme	ent through $5\frac{1}{2}$ " at 700', heavy mud to
190', displaced 20 sax ceme	ent through $5\frac{1}{2}^m$ at 190', heavy mud to
351, set rock and 10 sax ce	ement to bottom cellar.
Mudding and Cementing by Ha	alliburton Cementing Co.
	\mathcal{Z}
	District Conservation Agent
STATE CORPORATION COMMISSION BEC 4 1957 DEC 4 1957	Date 11-27-57
CONTION COMMISSION	Date 11-27-57
STIT CORPURATION 4 1957	LUCGING
DEC DIVISION	PLUGGING