Form CP-4

STATE OF KANSAS
STATE CORPORATION COMMISSION
Give All Information Completely
Make Required Affidavit
Mail or Deliver Report to:
Conservation Division
State Corporation Commission

WELL PLUGGING RECORD

| State Corporation Commission 212 No. Market | Gra | ham | Count | y. Sec T | 8S wp Rge | (E) (W) |
|--|--|---------------------------------------|----------------|--|---|---|
| Wichita, Kansas 67202 | Location as "N | E/CNW%SW%" | or footage fro | m lines SW SE | NE | (, , , , , , , , , , , , , , , , , , , |
| · · · · · · · · · · · · · · · · · · · | Lease Owner | <u>Cities Ser</u> | vice Uil | Company | | 201 |
| | Lease Name Holley LKC Unit North Well No. 301 Office Address Box 553 Russell, Kansas 67665 | | | | | |
| | 1 | | | | | |
| | Date well com | _ | | r Dry Hole) | | 2-10 1956 |
| 0 | 1 | | | | | 4 - 29 1970 |
| | | | | | | 4-30 1970 |
| | | nenced | | | | 5 - 21 1970 |
| | Plugging comp | | • E | | | <u>5-23 1970 </u> |
| | Reason for abas | ndonment of we | ll or producin | g formation | Depleted | |
| | 76 | 11 to -11 | . 3 . 3 | | 12 | -25 ₁₉ 69 |
| | i | | | st production | | re plugging was com |
| Locate well correctly on above Section Plat | menced? | | - the Conserv | adon Division of | TIS AGENCY DOLO | to programs was con |
| ame of Conservation Agent who supe | | | | ichols | | |
| roducing formation Lansing-I | <u>Kansas City</u> 1 | Depth to top $\frac{3}{2}$ | 692 Bottor | 3920 ' | Total Depth of | Well 3920 Fee |
| low depth and thickness of all water | , oil and gas formation | ns. | | | | |
| OIL, CAS OR WATER RECORD | os | | • | | c | CASING RECORD |
| FORMATION | CONTENT | FROM | то | SIZE | PUT IN | PULLED DUT |
| FURMATION | CONTENT | FRUM | | 8 5/8" | 2231 | None |
| | | - | | 5 1/2" | 3920 ' | 1179° |
| | | | | -/ | 5,20 | |
| | | | | | | |
| | | | | | | |
| | | ļ | ļ | | | |
| | | <u> </u> | <u> </u> | | | |
| | | | .1 | | | |
| Pumped in | 5½" casing re n (Down 8 5/8" Sx. Gel, 100 cement 4 sx. le to surface. | Surface P | ipe) 5 s | x. Hulls, Gel, 200Ns ment fillin n.8 5/8" | RECEIV CORPORATION C JUL 20 19 ERVATION DI Sechita, Kanso | OMMISSION 70 VISION |
| | rface Pipe. W | | | | 2-2- | \$ |
| Plugging | complete 11 A | .м. 5-23-7 | 0 | | · 20~ | 77) |
| | | | | | · · · · · · · · · · · · · · · · · · · | |
| | | | 1 | | | |
| | | | | | | <u> </u> |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | · · · · · · · · · · · · · · · · · · · | | | | |
| | | l description is nece | DACT | F of this about | | *************************************** |
| ame of Plugging Contractor | Knight Cas | ing Pullin | g Co. In | C • | | |
| ddress | Chase, Kan | | | | | |
| | | | | | | |
| TATE OF <u>Kansas</u> | COL | INTY OF R | 1155611 | | | |
| M. M. Hard | | | | ownor) or (rever | | of the above-describe |
| ell, being first duly sworn on oath, | | | | | | |
| bove-described well as filed and that | | | | | | |
| A CONTRACTOR OF THE PROPERTY O | • | (Signature) | | MINIS | faidin | |
| THE STATE OF THE S | | / nrangrarot/ | Ros 550 | | / | 665 |
| The state of the s | | | DOX 333 | Russell, | Kansas 07 | |
| SUBSCRIBED AND SWORN TO befo | re me this 17t | h day of | Jul | | , 19 | 0 |
| UBL\C | | | | | | |
| LOBLIO (48) | | | | imus d, /1 | y y | Notary Public. |
| Commission expires 10-5-7 | <u> </u> | 7. | • | | | z uono. |
| COUNTY | | • | | | | |

CITIES SERVICE OIL COMPANY IMPERIAL OL KANSAS, INC.

Well Completion Report

HOLLEY L-KC UNIT WORTH

Testing.

Well No. LOC. SW SE NE Sec. 29 Twp. 88 Rge. 24W

GRAHAM KANSAS State __ HOLLEN Pool

8-28-58

Moved in Franks #1. Pulled rods and tubing. Perf. 200' zone 3879-81 with 4 Jets per ft. Ran tubing with Imperial packer set at 3873. Dumped 500 gal. Form Gel down annulus. Acidized down tubing with 3000 gal. reg. Was unable to control acid. Displaced 2000 gal. on vacuum at end of treatment.

8-30-58

3 hr. swab test .8 BOPH. Removed Imperial packer. Perf. 140' zone 3818-20 with 4 Jets per ft. Set Baker retrievable plug at 3830.

8-31-58

Acidized with 500 gal. Gel-W. MP 250#. Swabbed 9 BOPD first hr. after swabbing 5 hrs. dropped to 18 BOPH.

9-1-58

Reacidized with 2000 gal. Gel-B. MP 150#. Swabbed back load. 4 hr. swab test 5.8 BOPH no wtr.

9-2-58.

Pulled Baker retrievable plug. Perf. 100' zone 3769-71 with 4 Jets per ft. retrievable bridge plug at 3780. Acidized with 500 gal. Gel-W. MP 350#. Swabbed back load. 3 hr. swab test 1.68 BOPH tr. wtr. Reacidized with 2000 gal. Gel-W. MP 250#. Swabbed back

STATE CORPORATION CON. APR 3 0 1970

9-4-58

CONSERVATION DIVISION off bottom.
Wichita, Kansar. Sun off bottom. 9-4-58

Wichita N DIVIS

12 hr. swab test swabbed a total of 110 BW + 45 BO. 10 BFPH 2 pulls permiss. 200° off bottom. Pulled Baker retrievable bridge plug. Perf. 35° zone 3718-20. Ran Baker retrievable plug at 3730. Acidized with 500 gal. Gel-W. MP 200# on vacuum at end of treatment. SBL

6 hr. swab test 5 BOPH no wtr. Ran tubing with Imperial packer set at 3830. Ran rods. Put well on pump.

11-20-58

Removed packer. Ran tubing to bottom. Put well on pumpl

DAKOTA BREAK-IN

3-31-62: Moved in Franks Unit #2. Pulled rods and tubing.

4-2-62: Ran tubing with Halliburton retr. plug and packer. Set plug at 2237. Found hole in casing at 2033. Set packer at 2018 and squeezed with 150 sax HA-5 cement. Displaced 125 sax at a standing pressure of 2000#. Reversed out remaining cement. Washed out cement to below perf. WOC 12 hrs. Pulled tubing with plug and packer. Running tubing and rods to place well back on pump.