DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission Conservation Division 800 Bitting Building Wichita, Kansas

Wichita, Kansas	
	FILE NO.
	LOCATION SE SE SE
	SEC. 21 TWP. 27S RGE. 2E
Dry Hole X Abandoned Oil Well	Abandoned Gas Well
I have today completed supervision of plug Jackson Lecuse Well No. 1 Lease (Dillon)	ging of:
Operator Bankoff Oil Company Addres	s P. O. Box 2301, Tulsa 1, Okla
Field Wildcat County	Sedgwick
Total Depth 3363 Feet.	
(Describe briefly the manner in which	h the well was plugged)
128 feet of 8-5/8 inch surf	qce casing circulated
with cement. Filled hole f	ull of heavy rotary mud
from 3363 feet to 128 feet.	Set plug and 15 sacks
of cement. Filled hole fu	ll of mud to 20 feet of
surface. Set plug and 6 sa	cks of cement at the surface.
Receircu 12/19/52	X D D in
	(1 /) / X a

PLUGUING
PLE SEE 2/127 R 2E

SOOK PAGE 44UM 38

District Conservation Agent

Date December 19, 1952