TO: V 10-26	API Number: 15-141-20,304
STATE CORPORATION COMMISSION	
CONSERVATION DIVISION - PLUGGING	SW SW NW /4 SEC. 06 , 09 S, 11 W
130 SOUTH MARKET, SUITE 2078	2970 feet from S section line
WICHITA, KANSAS 67202	4950 feet from E section line
Operator license# <u>3956</u>	Lease: B. DeMoss Well # 1
Operator: Brungardt Oil & Leasing Company	County: Osborne ////
Address: P.O. Box 871	Well total depth 3420 feet
Russell, Kansas 67665	Conductor Pipe: 0 inch @ 0 feet
	Surface pipe 8 5/8 Inch @ 216 feet
Aband. oil well, Gas well, Input well	l, SWD, D & A_ X
Plugging contractor: Shields Oil Producers	s, Inc. License# 5184
Advers Purell Person 67665	!
Address: Russell, Kansas 67665	
Company to plug at: Hour: P.M. Day: 26	Month: October Year: 1995
Plugging proposal received from: Burt Ber	144 B
Plugging proposal received from:	<u> </u>
Company: Shields Oil Producers, Inc.	Phone: 913-483-3141
ompany.	
	<u> </u>
	·
Plugging Proposal Received by: Herb Deines	:
Plugging operations attended by agent? All[] Part[] None[Y]
ringging operations accended by agent: Air	j, raret j, nonet a j
Completed: Hour: 1:00 P.M. Day: 26	, Month: October , Year: 1995
· · · · · · · · · · · · · · · · · · ·	,,
Actual plugging report:	
1st. Plug at 1000' w/25 sxs Anhydrite 97	6' - 1005'. RECEIVED
2nd. Plug at 775' w/100 sxs Dakota 466'	- 766'. STATE CORPORATION COMMISSION
3rd. Plug at 270' w/40 sxs Surface pipe	
4.5 -5 . 46. 446	to 216'.
4th. Plug at 40' w/10 sxs.	LOGIS ASSET 1 - 1 - 1 - 1
Rathole with 15 sxs.	NOV 1 3 1995 -13 -
Rathole with 15 sxs.	00000000000000000000000000000000000000
Rathole with 15 sxs.	NOV 1 3 1995 -13 -
Rathole with 15 sxs.	00000000000000000000000000000000000000
Rathole with 15 sxs. Mousehole with 10 sxs.	00000000000000000000000000000000000000
Rathole with 15 sxs. Mousehole with 10 sxs. Remarks: <u>Halliburton Cementing</u> .	MOV 1 3 1995 - 1 3 -
Rathole with 15 sxs. Mousehole with 10 sxs. Remarks: Halliburton Cementing. Condition of casing(in hole): GOOD BAN	CONSTRUCTION WITHITA KANSAS D Anhy.plug: YESx NO
Remarks: Halliburton Cementing. Condition of casing(in hole): GOOD BANGE BOTTOM Plug(in, place): YES_, CALC_, No.	MOV 1 3 1995 CONCLUS OF MICHITA KANSAS DAnhy.plug: YESXNO DAnhy.plug: YESX, NO
Remarks: Halliburton Cementing. Condition of casing(in hole): GOOD BANGE BOTTOM Plug(in, place): YES_, CALC_, No.	MOV 1 3 1995 CONCLUS OF MICHITA KANSAS DAnhy.plug: YESXNO DAnhy.plug: YESX, NO
Remarks: Halliburton Cementing. Condition of casing(in hole): GOOD BANG Bottom plug(in, place): YES , CALC , NO Plugged through TUBING , CASING	CONCURSION CONCURS SERVICES IN NO D Anhy.plug: YESX NO OX Dakota plug: YES_X , NO Elevation: 1866 GL
Ath. Plug at 40' w/10 sxs. Rathole with 15 sxs. Mousehole with 10 sxs. Remarks: Halliburton Cementing. Condition of casing(in hole): GOOD BAI Bottom plug(in, place): YES, CALC, No Plugged through TUBING, CASING I did[]did not [X] observe the plugging and the plugging states of the	MOV 1 3 1995 CONCUMPATION WITHITA KANSAS D Anhy.plug: YESX NO OX Dakota plug: YES_X , NO Elevation: 1866 GL