DISTRICT CONSERVATION AGENT'S REPORT

TO:

15-179-00180-00-00



FILE NO.

State Corporation Commission Conservation Division 211 North Broadway Wichita, Kansas

LOCATION SE NE SW
SEC. 11 TWP. 8 RGE 27
Dry Hole X Abandoned Cil Well Abandoned Gas Well
I have this date completed supervision of plugging of: Well No. 1 Lease Davis 11/1
Operator Aylward Drg Co & C.R.A. Address Aylward Drg Co Wichita, Kan
FieldCounty Sheridan
Total Depth 4000 Feet.
Plugging Contractor Aylward Drg Co
Plugging Contractor's License No.
Address
(Describe Briefly the manner in which the well was plugged) 8 5/8" at 365' circulated with cement.
Circulated hole with heavy mud, set cementing plug at 350',
1/2 sack hulls and 15 sax cement, mud to 40', set cementing
plug, 1/2 sack hulls and 10 sax cement to bottom cellar.
District Conservation Agent Date 5-11-56

PLUGD''G FILE SEC 11 T 8 R 27W BOOK PAGE 63 LIVE 10

RECEIVED
STATE CORFORMON COMMISSION

MAY 19.1936

CONSERVATION DIVISION