KCC OIL/GAS RÉGULATORY OFFICES

Date: <u>05/22/08</u>	District: <u>01</u>
	New Situation Lease Inspection
	Response to Request Complaint
	Follow-Up Field Report
Onewater License No. 5096	A DI Wall Number 15 125 24771 0000
Operator License No: 5086	API Well Number: <u>15-135-24771-0000</u> Spot: <u>SW-SE-NW-NW</u> Sec <u>35</u> Twp <u>19</u> S Rng <u>24</u> E / W
Op Name: Pintail Petroleum, Ltd.	
Address 1: <u>225 N Market Ste. 300</u> Address 2:	1260 Feet from N/ S Line of Section 950 Feet from E / ✓ W Line of Section
City: Wichita	GPS: Lat: <u>38.35986</u> Long: <u>99.94903</u> Date: <u>5/22/08</u>
State: Kansas Zip Code: 67202 -2024	Lease Name: Kerr 'RM' Well #: 2-35
Operator Phone #: (316) 263-2243	County: Ness
Reason for Investigation:	
Witness Alt.II	
Problem:	· · · · · · · · · · · · · · · · · · ·
None, cement circulated to surface	
	Drony
Persons Contacted:	RECEIVED KANSAS CORPORATION COMMISSION
Terson's Contacted.	
	JUN 0 6 2008
Findings:	CONSERVATION DIVISION WICHITA, KS
	, 10
8-5/8"@ 203'W/160sxs cement TD @ 4375'	
5-1/2" @ 4363'W/175sxs cement	
Port Collar @ 1562' cemented with 275sxs-s	md-1/4# flo seal-2%cc-10sxs went to pit
	·
Action/Recommendations: Follow	w Up Required Yes No 🗗 Date:
No ne-Alt,II requir eme nts have be en met.	
None-Alt-II requirements have been met.	
MAY 2 9 2008\) U/	
M	
KCC Dodge City	
Verification-Sources:	Photos Taken:
l branch branch	TA Program Pour Michael Major
	Courthouse By: Michael Maier
Other:	

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: 02/22/2008

Date: <u>05/22/08</u>		_	District	1:101	_	Licer	ise #: <u>5086</u>		
Op Name: <u>5086</u>	- -		Spot: <u>S</u>	W-SE-N	IW-NW	Sec <u>35</u> Twp <u>19</u>	_S Rng <u>24</u>	E W	
County: Ness			Lease N	Lease Name: Kerr 'RM'			Well #: <u>2-35</u>		
I.D. Sign Yes	No		ন	Gas V	enting _	Yes No		27	
Tank Battery Condi	<u></u>	le Overflow	ing	Pi Fluid		ft; Approx. Size	ft. x	ft.	
Pits, Injection Site Fluid Depth:	_ft; Approx. S	iize:ft.	. xft.		ltwater Pi ks Visible		ested for Leaks:	• • • N	
Oil Spill Evidence				Fi	owing Hol	es	İ		
Abandoned Well	Potential Polls	ıtion Problem	Yes No FO	Т	A Wells				
							j		
3.3			•	M	onitoring	Records			
Lease Cleanliness	_	- ET	1						
Very Good Sa	atisfactory	Poor Very		<u> </u>					
SWD/ER Injection Well		•	Ness 🖻	Į.		ons Yes No	C/CD A	80	
Permit #: Pr						; T/C Annulus:			
Permit #: Pr			horized: psi horized: psi			; T/C Annulus: ; T/C Annulus:			
	essure – Actu essure – Actu		horized: psi horized: psi			; T/C Annulus:			
	CSSGT C FICE	pos, 1240			181				
API Number	Footages	Spot Location	GPS		Well #		Well Status		
15-135-24771-0000	1260FNL 950FWL	SW-SE-NW-NW	38.35986-99.9	4903	2-35	New well, Alt.II com	pleted		
							i i		
						_			
								,	
	<u> </u>	<u> </u>			<u> </u>	1			