KCC OIL/GAS REGULATORY OFFICES

Date: <u>06/03/08</u>	District: 01			\$	Case	#:			
	New Sit	uation			Lease Ins	pection			
	Respons	se to Requ	iest		Complair	nt			
	Follow-	Up			Field Rep	oort .			
Operator License No: 4767	API Well Nur	nber: <u>1</u>	5-083-	21.555-0	000				
Op Name: Ritchie Exploration, Inc.				•		_S Rng <u>23</u> E / \sqrt{\sqrt{W}}			
Address 1: P.O. Box 783188					-	N/ S Line of Section			
Address 2:						E / W Line of Section			
City: Wichita						Date: <u>6/2/08</u>			
State: Kansas Zip Code: 67278 -3188	Lease Name:	Bell 27	٩		·····	Well #: 1			
Operator Phone #: (316) 691-9500	County: Ho	dgeman	L						
Reason for Investigation:									
Witness Alt.II									
Problem:					i				
None, cement circulated to surface						·			
Persons Contacted:									
Findings:									
8-5/8"@ 209'	•								
TD @ 4806' 4-1/2" @ 4799' W/200sxs cement									
Port Collar @ 1415' cemented with 300sxs 60/40-6% gel-1/4# flo seal,10sxs went to pit									
1. 5.1. 55									
	· · · · · · · · · · · · · · · · · · ·			<u> </u>					
Action/Recommendations: Follow	Up Required	Yes	No		Date: _				
Alt.II requirements have been met.						RECEIVED			
					К	ANSAS CORPORATION COMMISSION			
IDECEIVED						JUN 2 6 2008			
						JON 2 0 2000			
JUN - 9 2008						CONSERVATION DIVISION WICHITA, KS			
Verification Sources: Dodge City						Photos Taken:			
	TA Program								
	Courthouse	By: _	Michae	el Maier	·				
Other:		-							
Retain 1 Copy District Office					\ ^	•			

Send 1 Copy to Conservation Division

Date: <u>06/03/08</u>		_	District:	01		Licei	nse #: <u>4767</u>			
Op Name: <u>4767</u>			Spot: <u>C</u>	E/2-N	E-NE	Sec <u>27</u> Twp <u>24</u>	S Rng <u>23</u> [_E √ W		
County: <u>Hodgeman</u>			Lease Na	me: <u>Be</u>	II 27A		Well #: <u>1</u>			
1.D. Sign Yes	No		S	Gas V	enting [Yes No	······································	8		
Tank Battery Condi		ole Overflow	ing 🕤	Fluid		ft; Approx. Size	:ft. x	ft.		
Pits, Injection Site Fluid Depth:	_ft; Approx. S	Size:ft	. xft.	\vdash	altwater P	<u> </u>	ested for Leaks:	× n Y N		
Oil Spill Evidence				Flowing Holes						
Abandoned Well	Potential Poll	ution Problem	Yes No 🖂	П	A Wells		:	·		
Lease Cleanliness Very Good Sa	atisfactory	Poor Very	y Bad	М	onitoring	Records	i .			
SWD/ER Injection Well Permit #: Pr Permit #: Pr	essure – Actu	al: psi; Aut		Tubi	ng:	ions	1			
	essure – Actu		horized: psi			; T/C Annulus:				
Permit #: Pr	essure – Actu	al: psi; Aut	horized: psi	Tubi	ng:	; T/C Annulus:	; C/SP Annu	lus:		
API Number	Footages	Spot Location	GPS		Well #		Well Status			
<u>15-083-21,555-0000</u>	660FNL 330FEL	C-E/2-NE-NE	37.94028-99.82	734	1	New well, Alt.II com	pleted			
							:			
							i.			
							+			