

# KCC OIL/GAS REGULATORY OFFICES

Date: 06/10/08

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 4058  
Op Name: American Warrior  
Address 1: P.O. Box 399  
Address 2: \_\_\_\_\_  
City: Garden City  
State: Kansas Zip Code: 67846 -0399  
Operator Phone #: \_\_\_\_\_

API Well Number: 15-135-24,785-0000  
Spot: W/2-NE-NE-SE Sec 1 Twp 19 S Rng 22  E /  W  
2310 Feet from  N /  S Line of Section  
440 Feet from  E /  W Line of Section  
GPS: Lat: 38.42819 Long: 99.69753 Date: 6/10/08  
Lease Name: Kuehn Well #: 1-1  
County: Ness

**Reason for Investigation:**

Witness Alt.II

**Problem:**

None, cement circulated to surface

**Persons Contacted:**

**Findings:**


8-5/8" @ 227W/160sxs cement  
TD @ 4278'  
5-1/2" @ 4277'W/150sxs cement  
Port Collar @ 1369' cement with 160sxs-smd-1/4# flo seal-2%cc-10sxs went to pit

**Action/Recommendations:**

Follow Up Required  Yes  No

Date: \_\_\_\_\_

Alt.II requirements have been met



RECEIVED  
KANSAS CORPORATION COMMISSION

JUN 26 2008

CONSERVATION DIVISION  
WICHITA, KS

**Verification Sources:**

KCC Dodge City

Photos Taken: \_\_\_\_\_

- RBDMS
- T-I Database
- Other: \_\_\_\_\_
- KGS
- District Files

- TA Program
- Courthouse

By: Michael Maier

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

Form: 02/22/2008

Date: 06/10/08

District: 01

License #: 4058

Op Name: 4058

Spot: W/2-NE-NE-SE Sec 1 Twp 19 S Rng 22  E  W

County: Ness

Lease Name: Kuehn

Well #: 1-1

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines   
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No Ness

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-24,785-0000	2310FSL 440 FEL	W/2-NE-NE-SE	38.42819-99.69753	1-1	New well, Alt. II completed

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

Form: 02/22/2008