

# KCC OIL/GAS REGULATORY OFFICES

Date: 06/11/08

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 32657  
Op Name: Gateway Resources, LLC.  
Address 1: 2245 S. Crestway  
Address 2: \_\_\_\_\_  
City: Wichita  
State: Kansas Zip Code: 67218 -1312  
Operator Phone #: (316) 684-0199

API Well Number: 15-135-24,809-0000  
Spot: C-NW-SE-SE Sec 8 Twp 19 S Rng 24  E /  W  
980 Feet from  N /  S Line of Section  
1170 Feet from  E /  W Line of Section  
GPS: Lat: 38.40920 Long: 99.99356 Date: 6/11/08  
Lease Name: Buena Vista Well #: 1-8  
County: Ness

Reason for Investigation:

Witness Alt.II

Problem:

None cement circulated to surfae

Persons Contacted:

Findings:


8-5/8" @ 216'  
TD @ 4440  
5-1/2" @ 4439'W/15sxs cement  
Port Collar @ 1635' cemented with 160sxs-smd-1/4# flo seal-2%cc-15sxs went to pit

Action/Recommendations:

Follow Up Required  Yes  No

Date: \_\_\_\_\_

Alt.II requirements have been met



RECEIVED  
KANSAS CORPORATION COMMISSION  
JUN 26 2008  
CONSERVATION DIVISION  
WICHITA, KS

Verification Sources:

Photos Taken: \_\_\_\_\_

- RBDMS
- T-1 Database
- Other: \_\_\_\_\_
- KGS
- District Files

- TA Program
- Courthouse

By: Michael Maier

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

Form: 02/22/2008

Date: 06/11/08

District: 01

License #: 32657

Op Name: 32657

Spot: C-NW-SE-SE Sec 8 Twp 19 S Rng 24  E  W

County: Ness

Lease Name: Buena Vista Well #: 1-8

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines   
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No Ness

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-24.809-0000	980FSL 1170FEL	C-NW-SE-SE	38.40920-99.99356	1-8	New well, Alt. II completed

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

Form: 02/22/2008