

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission  
Conservation Division  
800 Bitting Building  
Wichita, Kansas

FILE NO. 121-21

LOCATION NE SE SW

SEC. 17 TWP. 26 RGE. 2E

Dry Hole X Abandoned Oil Well \_\_\_\_\_ Abandoned Gas Well \_\_\_\_\_

I have today completed supervision of plugging of:

Well No. 1 Lease Tjaden  
Operator Hannum Drilling Co. Address 1022 Union Nat'l. Bank Bldg.  
Wichita, Kansas  
Field \_\_\_\_\_ County Sedgwick  
Total Depth 3045 Feet.

(Describe briefly the manner in which the well was plugged)

The hole was filled with drilling mud to the bottom of the surface pipe, this being 125'. A wooden plug was placed at this point with 15 sacks of cement placed on top from 125' to 110'. The hole was then filled with drilling mud and another wooden plug was placed 5' down from the top and cemented with 5 sacks of cement.

PLUGGING  
FILE SEC 17-T-26  
BOOK PAGE 18 LINE 21

RECEIVED  
STATE CORPORATION COMMISSION  
NOV - 3 1951  
CONSERVATION DIVISION  
Wichita, Kansas

J.P. Roberts  
District Conservation Agent

Date 11-2-51