
FILE NO. 46-22

## DISTRICT CONSERVATION AGENT'S REPORT



TO:

State Corporation Commission Conservation Division 211 North Broadway Wichita, Kansas

wichita, Kansas	LOCATION SE SE NE
	SEC. 26 TWP 10 RGE 23
Dry Hole X Abandoned Oil Well	Abandoned Gas Well
I have this date completed supervision of plu	agging of:
Well No. lease Klenk	
Operator Davis Bros Add	ress 14 E 3rd Tulsa, Okla
FieldCou	nty_Graham
Total Depth 3890 Feet.	
Plugging Contractor Barnes & Sons	& Halliburton Co
Plugging Contractor's License No. 9	
Address	
(Describe Briefly the manner in 8 5/8" at 184' circulated with cemen	
behind - P.B. to 3687! - perforated	3663 <b>¹</b>
Filled with sand to 3650', set 4 sax	cement with dump bailer, pulled
$5165$ ' $5\frac{1}{2}$ " tp 1000', circulated hole	with heavy mud at 1000' with (40 sax
Gel) - displaced 20 sax cement throu	gh $5\frac{1}{2}$ " at 600', heavy mud to
1701, displaced 20 sax cement through	h $5\frac{1}{2}$ ", heavy mud to $35$ ! set
cementing plug and 10 sax cement to	bottom cellar.
Mudding and cementing by Halliburton	Co. Q
·	District Conservation Agent
Dat	



PLUGGING
FILE SEC 26 T 10 R 23W
BOOK PAGE 46 LINE 22