



DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
800 Bitting Building
Wichita, Kansas

FILE NO. _____

LOCATION CW 5W 7E

SEC. 8

TWP. 26

RGE. 2E

Dry Hole

Abandoned Oil Well _____

Abandoned Gas Well _____

I have today completed supervision of plugging of:

Well No. 1

Lease. Meyers

Operator Chas. Carlock

Chas. Carlock

Address 609 ~~Peter~~ ~~Blvd~~

Wichita

Field Fairview

Fairview

County Seelye

Seelye

Total Depth 2999

2999

Feet.

(Describe briefly the manner in which the well was plugged)

Rotary Mud to 110'

12 sq cement

Rotary mud to 10'

Cement in top of 8 5/8 Surface

8 5/8" Surface pipe cemented 7/8 99'

RECEIVED
Conservation Division
PLUGGING
STATES OF KANSAS
FILE NO. 15-173-00975-00-48
COP. 125-50-48
BOOK PAGE _____
KANSAS
1-27-50

NO Fees
District Conservation Agent

Date Jan 27, 1950

Jan 27, 1950

F